APR 0 8 1996

LAND CORNER RECORDATION CERTIFICATE

For corners in		ment of Act 74, Mich. P.F	A. 1970
Shiawassee (County)	MMISSION Located in:	Corner Code #	RECORDED
	,		95 NOV 22 PH 1: 20
A B I II A 10	T 0N D 0F	(M-11)	
1. Public Land Survey	T <u>8N_R2E</u>	(197-11)	REGISTUR OF DEEDS
	TR		Layer Shuster
	TR		SHIAWASSEE COUNTY MICH
2. Property Controlling	srR		
in Section	sTR		
3. Miscellaneous Property In Sec.	STR STR		Register of Deeds Stamp & File Number
Property in Sec.	·		ABCDEFGHIJKLM
4. Lot No	, Recorded Plat	·····	
5. Private Claims			2 6 5 4 3 2 1
			3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
			4 -7 -4 -8 -4 -9 -4 -10 -4 -11 -4 -12 -4
i Mark I VanRaemdonck	, in a field survey on October 18, 19	95, do hereby certify that under	5
requirements of P.A. 74. I	Michigan P.A. of 1970, the corner po	ints mentioned in lines 1 and 2	6 - 18 17 16 15 14 13 -
above were in conforman	ce with regulations and rules theref ons of the United States Department	ore as required in the current of the interior. Bureau of Land	7
Management or by a deci	ree of a Court of Law and/or that the	ne current points mentioned in	8 - 19 20 21 22 23 24 -
lines 3, 4 and 5 above w Surveyors or by a Decree	ere in conformance with the rules of a Court of Law; established, re	of the Michigan Board of Land -established, monumented, re-	9
monumented, recovered, f	ound as expressed below:	,	10 -30 -29 -28 -27 -28 -25
NOTE: Not more that	n 4 corners, all in the same to	wn and range.	11 12 31 32 33 34 35 36
may be recorded on t	his certificate.	•	12 31 33 34 35 36
A. Description of original	monument and accessories and/or su	ubsequent restoration:	13
1.) Original: Joseph Wan	npler. D.S.		
Monument: Woo	d stake		
Accessories:	Birch 14 S85°W 9 Sugar 9 N48°E 28		
	•		onck, L.C.R.C. recorded Liber 2, page 199, 9/5/79
2.) C.E. Smith, M.D.O.T., Monument: Foun	July 1962 Id 2" wood stake. Put in 1" iron rod		nt: Found 5/8" rerod ries: Same as no. 3 above
Accessories:	14" Box Elder S20°E 77.88'		
• •	SE corner Wingwall N30°E 67.30' T. pole S70°W 60.59'	•	onck, Survey recorded Liber 6, page 945, 8/13/93 at: 1/2" rerod with cap #24622
	123.87' North to SW corner Section	1.30	les: Same as no. 3 above.
	T8N-R3E (GLO = 1.87 ch. = 123.42)	*********	
) At Man Daamdanak Si	irvey recorded Liber 3, page 225, 6/1	4170	onck, Survey recorded Liber 6, page 795, 8/13/93
Monument: Foun	d 5/8* rerod	Worldmen	it: ½" rerod with cap #24622
Accessories:	N10°W 82.70' Road sign N60°E 67.10' SW cor. SW wingw		ies: Same as no. 3 above
	\$70°W 60.59' Power pole	- "	
	\$20°E 77.88° 14" Box Elder		
3. Description of corner e	vidence found and/or method applied	in restoring or reestablishing corn	ner:
ound ½" rerod with cap #:	24622 as referenced in no.'s 3, 4, 5 a	and 6 above. Checked with refere	nces in no. 2 above. Found no conflicting for Harrison Marker. Accepted this location as
hydence. Found brick, cro he careful and faithful per	petuation of the original corner location	on.	Tot Harrison Warker. Accepted this location us
C. Description of monume	nt for corner and accessories to perp	etuate locating the position of the	corner:
•	th standard Harrison Marker stamped		
65°W 60.46' Set N&T 24	4622 N. face utl. pole		and the state of t
20°E 57.52' Set N&T 24		!	Of MICH
35°E 67.11' SW edge S	W cor. of W. conc. wingwall	•	The second of th
ioπn 123.45' Pipe at SW	cor. Section 30, T8N-R3E		** MARK L. **
``	ΔPI	PROVED	* MARK L. * VANRAEMDONCK * LAND * SURVEYOR
	7 11 1		SURVEYOR &

IIRFR 10

Surveyor's Michigan License No. 24622

County Remonumentation
Peer Review Group
OCT 24, 1995 ML

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971, HEVISED MAY 14, 1975 REVISED JAN , 1983

24622