RURVEY 2 REMOTE MALE TO THE

SECTION

Signed by
Surveyor's Michigan Ligense No.

1999 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in										
Shiawassee (County)	Located In: Hazelton Twp	Comer Cade #	Kaya Grubba - Shi	l awass	Co.	REMO	N N	Page 10/0	6111 •: 1 of 5/1999 P-304	02:19P
1. Public Land Survey	T <u>8N R4E</u>	M-8	.c0							
2. Property Controlling Sin Section S 3. Miscellaneous S Property in Sec. S	T R T R T R T R	County Peer Peyle	umentation Regis	ster o	Deed	s Stam	p & File	Numb	er 	
		Conth L'Ship	61 16	۹ ۱ ا	В (O D	E F G	Э Н 1	JK	L M
4. Lot No, Recorded Plat 5. Private Claims		Co beer		2 3	6	5	4	3	2	1
I, John H. Rauser, P.S.				4 5	7	8	9	10	11	12
do heraby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					18	17	16	15	14	13
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as			5 a 8	19	20	21	22	23	24	
expressed below:				10	30	29	28	27	26	25
NOTE: Not more than 2 corner on this certificate.	s, all in the same	town and range, ma	y be recorded	11 12 13	31	32	33	34	35	36
 Standard 1/4 Corner, Section 24, T8N-R4E, Hazelton Township, Shiawassee County 1822 Wood post placed by J. Wampler, D.S.,										
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Standard 1/4 Corner, Section 24, T8N-R4E, Hazelton Township, Shiawassee County Found no evidence of original government accessories. Found no object at the position of M-8, milling and overlay has been placed on M-13 at this position. Calculated the position of M-8 mid-way and on line between M-9 and M-7, as recovered in the field. Measured distance between M-9 and M-7 = 5285.98, mid-way calculates to be 2642.99'. This position measures 0.15' less than the position from the 1993 record, which is assumed to be set at the same single proportionate measure. The angle measured from M-9,M-8 to L-8 = 90°20'17", 1993 record = 90°20'03". The occupation to the West at this position is a tree row, the center line of which was tied in the field and is located 5'± South of the calculated position. A fence occupation to the East is 281.4' ± N of this position, the mean closing jog using the M-9, A-9 jog of 250.60 and the M-7, A-7 jog of 308.22' calculates to be 279.41'. We located, as closely as possible, the path of the original drain before it was re-located for the M-13 crossing. GLO call for drain = 1841.4' (27.90 chains) we measured 1810'± to apparent old crossing. The drain has been relocated for the crossing of State Highway M-13 and cannot be considered a reliable accessory. We recommend accepting the calculated position as the a careful and faithful re-establishment of the lost corner M-8 by single proportionate measure and place a ½" re-rod under a 5/8" re-rod welded to a standard Shiawassee County Harrison monument removable top and a custom 3" tall monument box which is bolted into the concrete pavement below the asphalt overlay.										
C. Description of monumer Standard 1/4 Corner, Se Set a ½" re-rod under a custom 5" tall monume approved by the Shiaw	ection 24, T8N-R4 a 5/8" re-rod weld ent box which is b rassee County Pe	E, Hazelton Townsh ded to a standard S olted into the concr eer Review Group.	ip, Shiawassee Cou hiawassee County	<u>untv</u> Harri	son m	onume	nt remo	vable	top and	
	ike w/tag #39096 ike w/tag #39096		n ·	l:	111	OHN H				