## SURVEY & REMONUMENTATION



FEB 0 8 2001

## SECTION

## 2000 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74,

FILE NO PAGE N Mich. P.A. 1970 For corners in: ARBELA TWP. 00 DEC 19 PM 1:36 Corner Code # Tuscola Located In: 1. Public Land Survey 10N R 7E K-5 2. Property Controlling \_\_\_\_\_Ť\_\_\_\_ \_\_\_\_\_\_\_\_T\_\_\_ in Section Register of Deeds Stamp & File Number 3. Miscellaneous \_\_ T\_\_ \_ R \_\_\_\_ T\_\_\_\_


4	Lot	No.		Recorded	Plat
₹.	LUL	NO.	 ,	recolueu	FIAL

5. Private Claims

Property in Sec.

I, <u>Kari M. Lohela</u>, in a field survey on August 29, 20 <u>00</u> do hereby state that under requirements of P.A. 74, Nichigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



RECEIVED FOR RECORD

Description of original monument and accessories and/or subsequent restoration:

1822 G.L.O. NOTES, JOSEPH FLETCHER, D.S., SET CORNER POST TO SECTIONS 11-12-13 & 14, ELM 24 N 64 W 7, ELM 20 N 87 E 19

AUG 22, 1888, JOHN TESKEY, SURVEYOR, STAKE ESTABLIHED AT CORNER, MAPLE 4 S 44 ½ N 55 ½

APRIL 20, 1972, LCRC P.16, ARBELA TWP., GERALD R. MCKELVEY, PS 19001, SET PK NAIL AT CENTERLINE OF MILLINGTON ROAD AND ON BRIDGE OF WEST SECTION LINE AS ESTABLISHED BY RECORDED PLAT OF CANDICE SUBDIVISION, SE 25.50' CENTER STREET SIGN, NE 13.04' SOUTH CORNER HARDWARE, NW 41.50' CENTER STOP SIGN (PLAT CONTAINS NO INFORMATION PERTAINING TO CORNER K-5)

OCT. 8, 1976, LCRC P.53, ARBELA TWP., ROBERT TOMMER, PS 22444, STATES "WITNESSES FOUND TO BE ERRONEOUS. FOUND T IRON ON SURFACE AND 3/8" ROD 5" UNDER PAVEMENT, ADDITIONAL RESEARCH SHOWED TIRON WAS SET OVER PK NAIL WHICH WAS A TRAVERSE POINT. WITNESSED 3/8" ROD", S 45 E 42.50' TOP CENTER 4' CMP, N 30 W 42:80' STREET SIGN POST, S 35 W 73.00' TOP CENTER TELE. RISER

NOV. 19, 1992, SURVEY L.636 P.884, JONATHAN FIELD, PS 37276, FOUND 1/2" ROD, N 79 E 13.30' FOUND T IRON, N 30 E 42.80' ROAD SIGN POST, S 45 E 42.50' FOUND NOTCH TOP CENTER S. END 48" CMP, N,50 E 40.80' FOUND NOTCH TOP CENTER N. END 48" CMP, N 45 W 81.65' FOUND NAIL & TAG #11192 SE FACE P.P., S 30 W 73.30' TOP CENTER PHONE RISER The second secon

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND BENT 1/2" REBAR IN MONUMENT BOX. RECOVERED 5 ACCESSORIES WHICH INDICATES THAT 1/2" REBAR IS IN SAME POSITION AS 1992 SURVEY AND 1976 LCRC CITED ABOVE.

ACCEPTED FOUND 1/2" REBAR AS BEST AVAILABLE EVIDENCE OF ORIGINAL CORNER POSITION.

The state of the s

## K-5 T10N-R7E

Description of monument for corner and accessories established to perpetuate locating the position of C. Descrithe corner:

REMOVED 1/2" REBAR AND PLACED STANDARD BRASS CAP STAMPED K-5, T10N-R7E, OVER 5/8" X 24" IRON ROD, ENCASED CAP AND ROD IN CONCRETE IN EXISTING MONUMENT BOX.

N 55° E, 40.68' FOUND NOTCH IN CROWN AT N. END 48" CMP CULVERT

N 82° E, 13.30' FOUND T IRON ON CENTERLINE OF MILLINGTON ROAD

S 45° E, 42.67' FOUND NOTCH IN CROWN AT S. END 48" CMP CULVERT

N 44° W, 82.05' SET REMON. TAG & NAIL IN NE FACE OF UTILITY POLE

N 22° W, 43,35' FACE OF STEEL ROAD SIGN POST

