# **SURVEY &** REMONI IMENITATION

FEB 08 2001

#### 2000 REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

RECEIVED FOR RECORD LIBER HO. PAGE NO. FILE NO #111 Millington 60 DEC 20 Pi 2: 52

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

ansy morrow

For corners in: MILLINGTON TWP. Corner Code # **TUSCOLA** Located In: (County) 1. Public Land Survey T 10N R 08E K-8 2. Property Controlling in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. 1 A DEFGHIJK \_, Recorded Plat 4. Lot No. 2 5. Private Claims 4 1 3 4 7 Q 10 11 12 JONATHAN M. FIELD **AUGUST 17** , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land 6 18 17 16 15 14 13 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 19 20 2.1 22 23 24 8 9 Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 30 29 27 28 25 26 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 12 31 32 33 34 35 36 on this certificate. 13 Description of original monument and accessories and/or subsequent restoration: 1822 GLO; FLETCHER D.S.; SET POST; BEECH 16 N1/4E 17 LKS, BEECH 10 S89W 16 LKS. 1882 TESKEY, C.S.; PG.14-5; STAKE AT CORNER; NO WITS GIVEN 1973 ROWE ENG.; ROWE, P.S. #11192; SURVEY, L.2 PG.415; 1/2" ROD; S75°W 30.30' TAG IN APPLE, S40°W 66.30' TAG IN 10" MAPLE, EAST 33.00' "T" IRON 1982 DUNTON LAND SURVEYING; DUNTON, P.S. # 23503; SURVEY, L.527 PG.1441; FND. 5/8" ROD IN MON BOX; EAST 11.5' EDGE OF PAVEMENT, WEST 11.0' EDGE OF PAVEMENT, S25°W 147.15 TAG IN P.POLE

1982 DUNTON LAND SURVEYING; DUNTON, P.S. # 23503; SURVEY, L.529 PG.1416; SAME AS 1982 SURVEY

1987 KAY ENG.; BROWN, P.S. #24588; SURVEY, L.578 PG.721; SAME AS 1982 SURVEY

1992 ROWE ENG.; FIELD, P.S. #37276; SURVEY, L.632 PG.1335; FND. 5/8" ROD IN MON BOX; S25°W 147.15' NAIL W/TAG IN P.POLE, N80°E 63.62' NAIL IN 8" ELM, WEST 59.20' NAIL IN 8" ELM, S80°E 98.68 NAIL IN TWIN 8" ELM

1993 ROWE ENG.; FIELD, P.S. #37276; SURVEY, L.645 PG.950; SAME AS 1992 SURVEY 1994 ROWE ENG.; FIELD, P.S. #37276; SURVEY, L.667 PG.987; SAME AS 1992 SURVEY

Description of corner evidence found and/or method applied in restoring or reestablishing corner 2000 ROWE, FIELD, P.S.#37276; FND. 3/4" PIPE IN MON BOX; 0.5" W. OF C/L SHĚRIDAN RD., FENCE & TREE LINE TO E. & W.; RECOVERED 3 PREVIOUS WITS WHICH INDICATE THAT FND PIPE IS IN SAME POSITION AS 1982 SURVEY CITED ABOVE.

## ACCEPTED FND PIPE IN MON. BOX AS BEST AVAILABLE EVIDENCE OF ORIGINAL CORNER POSITION.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" ROD W/ REMON CAP STAMPED K-8 T10N R8É INSIDE FND. PIPE, ENCASED ROD, CAP & CONC. IN MON BOX OF MICH

S25°W 147.15' NAIL W/TAG #11192 IN E. FACE P.POLE

APPROYED

N80°E 63.62' NAIL IN S. FACE 8" ELM

WEST 59' CENTER OF 10" ELM STUMP

S80°E 98.68' NAIL IN S. FACE TWIN 10" ELM

N70°E 54.94' NAIL W/ TAG IN S. FACE 8" ELM

taxeta Signed by Surveyor's Michigan License No

\_Date\_\_\_//-/0 -2000

REVISED MAY 14, 1918 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993

**NAHTANOL** 

M. FIELD

PROFESSIONAL

SURVEYOR 37276 OFESSI



FEB 08 2001

SECTION



### K-8 T10N-R8E

10019 500

