FEB 08 2001

SECTION

2000 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECEITED			
LIBER JO.	PA	GE N	0
. FILE NO. II IL	Q_I	Mill	rothor

00 DEC 20 PM 2: 41

Chrom Michael

For corners in: MILLINGTON	I TWP.	1		V	ŢŲSĆ <u>ē</u>	LA CO'	FITY		
TUSCOLA (County)	Located In:	Corner Code #			K F OGS -	in tri	,11 (11 3		
1. Public Land Survey	T_10N_R_08E TR TR R	<u>L-1</u>							
Property Controlling in Section S Miscellaneous S Property in Sec. S	T R T R T R T R T R T R T R T R T R T R		Register of Deeds Stamp & File Number						
4. Lot No, Recor 5. Private Claims	ded Plat		1 ² 2 3	A B	5 D	E F (Э Н 1	J К 2	1
			4	7	. 8	9	10	11	12
do hereby certify that under require in lines 1 and 2 above were in c	ements of P.A. 74, Michiga onformance with regulation	rvey on <u>AUGUST 17</u> 20 <u>00</u> an P.A. of 1970, the corner points meins and rules therefore as required	in the	. 18	17	16	15	14	13
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			land58 ree ofa	19	20	21	22	23	24
Court of Law; established, re- expressed below:	established, monumented	d, re-monumented, recovered, fou	nd as	30	29	28	27	26	25
NOTE: Not more than 4 corn on this certificate.	ers, all in the same tov	vn and range, may be recorded	11 12 13	31	32	33	34	35	36
GLO; NOT SET		and/or subsequent restoration:	ON: FASI	۲ <u>4</u> 9 52	' S 1/4	COR S	SEC 36	T11N	

R8E, S2W 613.48' RAILROAD SPIKE, S88W 31.08' FND T-IRON

1981 LEACH ENG.; LEACH, P.S. #7236; LCRC PG.56; SAME AS 1981 SURVEY (SET AT EXTENSION OF OCC. N-S 1/4 LINE & N. SECTION LINE)

1994 HURON SURVEYING, BROWN, P.S. # 24588, SURVEY, L.665 PG. 693-4; FND. 1/2" ROD; S10E 25.59' SPIKE W SIDE 7" OAK, EAST 10.80' SPIKE NORTH SIDE 12" BIRCH, N15E 13.55' SPIKE W SIDE 6" BIRCH

Description of corner evidence found and/or method applied in restoring or reestablishing corner: ROWE; POWELL, P.S.; FND. 1/2" ROD W/ CAP #24588 1.12' N. OF S. LINE OF T11N-R8E; RECOVERED 1 PREVIOUS WIT WHICH INDICATES THAT FND. ROD IS IN SAME POSITION AS 1981 SURVEY CITED ABOVE. 2000

PREVIOUSLY ESTABLISHED
OF CORNER POSITION (NOW HOLDING AS ACCEPTED FND. ROD AS BEST AVAILABLE EVIDENCE OF AMENDED MONUMENT).

Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET STD. REMON MONUMENT STAMPED L 1 T10N R8E ON S. LINE OF T11N-R8E (CAP STAMPED P.S. 37276) \$85°W, 29.74' FND. T-IRON

N86°E, 50.89' FND. TUSCOLA CO. MONUMENT AT L-13 T11N-R8E

SOUTH, 1.12' FND. 1/2" ROD W/CAP #24588

Mark Signed by Surveyor's Michigan License No.

Sug de Frans angr

OF MICH MARK W. POWELL **PROFESSIONAL** SURVEYOR

44298





FEB 08 2001

SECTION



L-1 T10N-R8E

