1995 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE 1970

			Filing Requirement of Act 74, Mich. P.A.
For corners in	Tuessis	Tarmakia	

Tuscola Township Tuscola Located In: Corner Code ##

T 11N R 7E Public Land Survey В

Property Controlling R in Section __ T _

Miscellaneous _ T __ Property in Sec.

Register of Deeds Stamp & File Number

_ , Recorded Plat _ Private Claims

I. Kenneth D. Dunton in a field survey on August 13 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

3 10 12

Description of original monument and accessories and/or subsequent restoration:

1821 G.L.O. Notes Joseph Wampler, D.S. Pine 54" corner to Sections 1 & 12.

no assessories given.

Sept.30,1940 Site plan by M.S.H.D. for M.C.R.R., crossing structure in Village of Vassar, Section 7,T11N-R8E. Plan indicates section corner to sections 1 & 12 as being 2585.4' North of iron stake at East 1/4 corner Section 12, T11N-R7E and on old fence line East. (Note: In 1989 K.D. Dunton found P.K.nail & 11192 tag at approximate location of corner to 1 & 12 as indicated above.)

Section A continued on back of this form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found P.K. nail at 2585.67' North of corner M-4, TIIN-R7E. No evidence of 3/4"pipe per Liber 1,Page 35 & Liber 546, Page 267. Neither P.K. nail or 3/4" pipe location falls proportional or relative to other corners along the Township Line, found no other evidence. Set corner M-3 TIIN-R7E at split of measured mile. Held P.K. at 2585.67' North of M-4 for line M-4 to M-3 as this line appears to have existed since 1940. Unable to establish Town line from Original Plat of Vassar.

DEC - 11995

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set concrete monument with standard brass cap stamped corner M-3, T11N-R7E. Set monument box over monument.

S54°53'E 37.92' Found 1/2" rerod & cap # 11192.

\$39°40'E 71.21' Found 1/2" rerod & cap # 23503.

S11°06'E 99.55' NE cor. North end Easterly concrete barrier wall on R.R. overpass.

" Westerly S15°48'W 73.20' NW

S15°48'W 73.20' NW " " Westerly S00°28'E 56.00' Found P.K. nail per R.R. plans.(prev.noted as being cor.to sections at apparent cor. A-3,T11N-R8E. programmed to

23503

KENNETH D DUNTON LAND URVEYOR

Surveyor's Michigan License No.

<u>APPROVED</u>

POFESSIONEMEDIAN.

Section A continued:

May 21.1974 Survey by John W. Martin, L.S. # 4699, recorded in Liber 1 of Surveys on Page 35, Tuscola County records. 3/4" pipe. N.W. 38.72' to face T.pole, N.E. 76.20' to ctr.oil line marker, N.W. 74.75' to ctr. oil line marker. (oil line markers painted orange & white)

October 1, 1984 Survey by Lionel Roy Emery, R.L.S.# 24593, recorded in Liber 546 on Page 267, Tuscola County records. 3/4"pipe. Accessories same as Martin, Liber 1, Page 35.

DRAFTERS NOTE: The 3/4" pipe noted above would lie approximately 356.5' North of the corner now monumented as corner M-3, TllN-R7E.

