SUMYEY & REMONUMENTATION (

APR 2 5 1995

COMMISSION

1994 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Vassar		Requirement of Act 74, I	Mich. P.A. 1970	_ < 9 T F R
Tuscola	Located In:	Corner Code=	#	ECEIVEU IBER NO. ILING NO. 94 DEC - VIRGINIA TUSCOL REGISTE
(County)				NO RO
1. Public Land Survey	<u>T 11N</u> R			35 - X 3
	T R T R			FOR RECORD PAGE NO FOR RECORD PAGE NO FOR RECORD PAGE TWP. PM 4: 25 H. HGL ARET A COUNTY A COUNTY A OF DEEDS
	T R			PAGE PAGE TOUNT F DEED
2. Property Controlling	S T R S T R			BY 25 No Beauty
in Section 3. Miscellaneous	S R			Deeds Stamp & File Number
Property in Sec.	S			Deeds Stamp & Fire Number
4. Lot No	Recorded Plat			
5. Private Claims			A B	C D E F G H I J K L M
			3 3	5 4 3 2 - 1 - 1
Kannath D. D			4 - 7-	8101112
do bereby certify that under r	 in a field survey on equirements of P.A. 74. Mich 	Oct. 15 nigan P.A. of 1970, the corner point	nts mentioned	
in lines 1 and 2 above were	in conformance with regul	ations and rules therefore as re es Department of the Interior, B	equired in the	17 16 15 14 13
Management or by a decree of	of a Court of Law and/or that	the corner points mentioned in I	ines 3, 4 and 5	20 21 22 23 24
Court of Law; established,	~	in Board of Land Surveyors or by ited, ire-monumented, recover		
expressed below:			10 _30-	29 -28 -27 -26 -25
on this certificat		town and range, may be re	12 31-	32 33 34 35 36
A Description of origina	I monument and access	ories and/or subsequent res	toration:	
- · · ·		·		
1821 G.L.O. Notes Joseph Wampler, D.	April 18	98 . Teskey, Surveyor	Oct. 27, 1990 Sur	rvey by Kenneth D. Duntor orded in Liber 608 on Pag
Set 1/2 mi. post		ohn A. Teskey	1145 & 1146, Tuse	cola County records. Fnd
Pine 40 S 50 E 3 Hem 13 N 50 W 7	from B.T		iron rod in place	. Field notes indicate
Hem 13 N 50 W 7	MO acces	sories given.		ed with 1/2" rod. West cor. Sec. 3, T10N-R8E.
		•	North 33' rod & o	cap #23503.
		·	N05°W 39.2' R.R.	& disk #11192 in p. pole tie cor. post.
B. Description of corner	evidence found and/or r	nethod applied in restoring o	or reestablishing corner:	V. C.
Found 1/2" x 18" i	ron rod & 1" x 36	" pointed iron rod b	elow 1/2" rod.	
Accepted 1/2" & 1"	iron rods as the	proper position of	the original corne	er.
		•		•
				Ž.
				;
C. Description of monum	ent for corner and acces	ssories established to perpe	tuate locating the position	n of the corner:
Removed 1/2" and 1	" iron rods and pi	laced 36" concrete m	onument with stand	ard brass cap
NO5°56'W 39.92' se	3, IIIN-R8E. Plac t T.C. Remon. tag	ced monument box ove & spike in E. face	r monument. R.R. tie cor. post	
NO1°24'W 33.00' fnd	d. 1/2" rod & cap	#23503.	·	•
\$74°45'W 127.35' fi	a. #11192 tag & sp nd. 1/2" iron rod	oike in NE face p. po at approximate road	R.O.W. line.	
S89°45'W 122.14' fr	nd. 1/2" iron rod	at apparent Cor. H-	1, T10N-R8E.	AND OF BILLIAM
•				A CENNETU - A
,	\sim \sim \sim \sim	T A	•	* KENNETH D.\T\
15.			ate November 21	EQUA SUNVEYOR FOR
Signed by		APPROVED	ate November 21	No. 23503
Surveyor's Michigan Licen	se No. <u>23503</u>	11-21-94	FORM APPROVED BY MICHIG	2 0 1
		Qm.	1	REVISED JAN., 1983

