$\sqrt{r_{\rm i}/r_{\rm i}^2}$ 

1999 REMONUMENTATION PROGRAM * COPY # # _
LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Vassar Township
LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970  Tuscola Located In: Corner Code #
1. Public Land Survey
T
Register of Deeds Stamp & File Number  A Lot No. Recorded Plat
4. Lot No, Recorded Plat
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.
A. Description of original monument and accessories and/or subsequent restoration:  June, 1822 G.L.O. notes, Joseph Fletcher, D.S. Set corner to Secs. 23, 24, 25 & 26, Beech 12" S80°W 10 links, Hemlock 10" S70°E 10 links. March 17, 1892 Survey of Sec. 25 by G. B. Felton, County Surveyor, set from measurements, Beech 15" S15°W 219 links, Pine 7" N48 1/2°W 141 links. July 3, 1896 Survey of Sec. 23 by Edward L. Teskey, County Surveyor, established proportionate distance by Felton, Beech 14" S17 1/2°W 218 3/4 links, Pine 8" N50 3/4°W 141 1/4 links. April 8, 1898 Survey of Sec. 24 by G. B. Felton, County Surveyor, prev. set, Beech 15" S15°W 219 links, Pine 7" N48 1/2°W 141 links. Dec. 1, 1898 Survey of Sec. 26 by Edward L. Teskey, County Surveyor, set by John A. Teskey.
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found "T" iron in monument box and accepted same as the best evidence of the original corner position.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  Removed "T" iron & perpetuated with 5/8" iron rod and standard brass cap stamped K-9, T11N-R8E. Encased rod & cap in concrete in monument box.  N45°E 43.65' set remon. tag & nail in NW face tele. pole (fnd. nail & cap SW face), S25°E 88.70' set remon. tag & nail in NE face 8" Maple in Maple clump. S60°W 73.81' set remon. tag & nail in NW face Power Pole (fnd. nail & cap in NE face). N45°W 50.82' set remon. tag & nail over #37276 tag in E. face 30" White Pine.
Due to the untimely illness of Mr. Emery, I, Kenneth D. Dunton, P.S. #23503 have reviewed Mr. Emery's field notes and have prepared this form.
Signed by Date 12 THENTETH D. *
Surveyor's Michigan License No. 23503  APPROVED  APPROVED

 $_{i}, _{i})$ 

Feb., April & Sept., 1971 L.C.R.C. Page 12 by David T. Rowe, P.S. #11192, found P.K. nail in asphalt, N40°E 43.24' nail & cap in P. Pole, S70°E 36.58' nail & cap in 8" tree, S50°W 73.24' nail & cap in P. Pole. July 20, 1971 Survey L-1, P-530 & 531 by David T. Rowe, P.S. #11192, "T" iron, accessories same as L.C.R.C. Page 12. Jan. 4, 1974 Survey L-438, P-791 & 792 by David T. Rowe, P.S. #11192, fnd. P.K. nail, accessories same as Survey L-1, P-530 & 531. Aug. 6, 1974 Survey L-445, P-735 by David T. Rowe, P.S. #11192, object and accessories same as Survey L-438, P-791 & 792. May 30, 1975 Survey L-452, P-652 through 655 by James A. Beck, P.S. #21559, same object and accessories as Survey L-445, P-735. May 12, 1977 Survey L-474, P-248 & 249 and April 18, 1977 Survey L-474, P-260 & 261 by Kenneth D. Dunton, P.S. #23503 (with Rowe Eng.), same object and accessories as Survey L-452, P-652 through 655 with the addition of S40°W 65.10' to 6" Cedar tree. June 7, 1978 Survey L-488, P-875 & 876 by Kenneth D. Dunton, P.S. #23503 (with Rowe Eng.), object and accessories same as Survey L-452, P-652 through 655. June 30, 1978 Survey L-530, P-81 & 82 by David T. Rowe, P.S. #11192, object and accessories same as Survey L-452, P-652 through 655. June 12, 1985 Survey L-551, P-1124 & 1125 by Anne E. Wilson, P.S. #30107, found "T" iron in asphalt, N45°W 50.61' face 2" White Pine, N30°E 43.36' nail & cap in Power Pole, S50°E 46.22' center top cable closure, S45°W 41.15' center top 6" double stump. March 3, 1997 Survey L-736, P-906 & 907 by Jonathan M. Field, P.S. #37276, found T-iron in mon. box, N40°W 50.84' nail & tag #37276 in E. face 30" Pine, N45°E 43.37' nail & bottle cap in S. face T. Pole, S20°E 85.44' nail & tag #37276 in W. face 12" Poplar, S65°W 73.31' nail & bottle cap in NE face P. Pole.

## Section 24 1822 Fletcher 2633.4' 1822 Fletcher 2633.41 1892 Felton 1892 Felton 2604.36 2632.741 1999 Emery K-9 2644.64' 2655.15' 1999 Emery M-9 HANES ROAD LL9 Section line 1975 Rowe 1999 Emery 86°36'42" 1999 Emery 93°21'46" 1999 Emery 179°00'09" 2676.30 2694.98' 2694.94' 2694.81' 67 56 86°36'52" 2506. 2606. lownship line Fletche Felton Wi.1son Dunton Emery tion 1822 1892 1975 1985 1999 SECTION 25, T11N-R8E 1999 Emery 179°57'53" 1993 Dunton Unadjusted error of M-10180°00'00" closure = 1/24,929. Adjusted compass rule method. 60, 33 76.30 2606. 2606. Dunton Emery Emery Felto Beck 1993 Dunton 1971 Rowe 92°18'15" 1822 1892 1975 Calculated 1993 1999 Emery 180°01'07" 1975 Beck 1999 Emery 92°18'48" 179°59'57 180°12'45" 1999 Emery 92°18'42" 1999 Emery ∰-M-11 K-11 Section line 11 88°44'41" 1822 Fletcher 1892 Felton 2627.79 1822 Fletcher 2590.831 1892 Felton 2590.831 1975 Beck 2605.21' 1978 Kay 2592.781 1999 Emery 2605.081 1999 Emery 2592.691 BROWN ROAD

Section

MANUAL PROPERTY OF THE PARTY OF

36

69