MAY 2 0 1997

1996 REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

engle of	BUSINOW.	
For corners in	Koylton	Twp.

Property in Sec.

Corner Code # Located in: Tuscola (County) 1. Public Land Survey NR10E 2. Property Controlling in Section 3. Miscellaneous


7 Ë

Register of Deeds Stamp & File Number

___, Recorded Plat ____ 5. Private Claims

I, Kenneth D. Dunton in a field survey on May 11, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Aug. 23, 1882 John A. Teskey, Co. Surveyor Sec. 31 TllN-RllE G.L.O. 1834 Harvey Parke. D.S. Set Post Cor. Secs. 25 & 36 Hemlock 20 N14W 18 Hemlock 20 N14W 18 2 S 22 3/4E 106 1/2 Maple 16 S55W 14 2 N42 1/2W 93 1/2 Beech Corner M-11, T11N-R10E

Dec. 10, 1973 Survey by David T. Rowe, Land Surveyor #11192, Liber 437-Page 347. N50°W 55.59' nail & cap in 36" Maple. nail & S50°E 86.01' cap in P.P. N45°E 51.64' nail & @ in 24" Maple.

Section A continued on back of form.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" rod in 3/4" pipe in rock pile 24" deep. Held fnd. rod & pipe as the best evidence of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Removed rod & pipe and placed standard monument stamped M-11, T11N-R10E.

Placed mon. box over monument.
S27°W 55.27' set T. C. Remon. tag & spike over spike fnd. in NW face T. pole

S63°W 111.12' set T. C. Remon. tag & spike in N. face P. pole.
N63°W 56.79' set T. C. Remon. tag & spike in S. face 42" Maple, fnd. bottle
cap & nail in SE face at 55.5'±.

cap & nall in SE face at 55.5 ±.

N55°E 52.88' set T. C. Remon. tag & spike in SE face 36" Maple.

S55°E 86.38' set T. C. Remon. tag & spike in NE face P. For Michigan bottle cap & nail in NW face at 86.1 ±.

Note: This corner is common with M.11, T11N-R10E.

Signed by Rennetted Division of the corner of the

Signed by Surveyor's Michigan License No.

4 * LAND

REVISED MAY 14,1975
REVISED JAN. 1983
REVISED OCT., 1995

/ FORM APPROVED BY MICH

January, 1974
L.C.R.C. form filed by David T. Rowe, Land Surveyor #11192, Page 10,
Koylton Township.
Set "T" iron as occupied using fences & road.
Same accessories as L-437, P-347.

Aug. 4, 1977
Survey by Robert G. Kay, Land Surveyor #14096, Liber 476-Pages 948 & 949.
Fnd. "T" iron.
Same accessories as L.C.R.C. Page 10.

Aug. 23, 1978
Survey by Kenneth D. Dunton, Land Surveyor #23503, Liber 490-Page 679.
"T" iron.
Same accessories as L.C.R.C. Page 10 except Maple N45°E labeled as 27".

Sept. 20, 1985
Survey by Earl E. Gravlin, Land Surveyor #23510, Liber 557, Page 793.
Fnd. 1" pipe.
N50°W 55.59' 36" Maple.
N45°E 51.64' 27" Maple.
S50°E 86.01' P.P.

May 7, 1991 Survey by John A. Milletics, Land Surveyor #25859, Liber 614-Page 1000. No mention of object fnd. or set or accessories.

