



OCT 2 0 1994

4. Lot No.

5. Private Claims

## 1994 REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE

For corners in Koylton Township Filing Requirement of Act 74, Mich. P.A. 1970				A. 1970 P. T. C. R. C. R
-	TUSCOLA (County)	Located In:	Corner Code :##	DEIVEL
1.	Public Land Survey	T 11N R 11E T R T R	G-13	H. Holar A County
2.	Property Controlling in Section	S T R S T R		12 12 05 05 05 05 05 05 05 05 05 05 05 05 05
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

Kenneth D. Dunton in a field survey on <u>May</u> 21 , 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1834 G.L.O. Notes Harvey Parke, D.S. Set post corner Sections 33 & 34 Cedar 12" N75 1/2°W 34 links Cedar 9" N75°E 19 links

· 1957-59 M.S.H.D. road plans Project No. 44081 & 74041, sheet 8 P.I. Sta. 241+90.20. 1" pipe N68°W 63.96' tele. p. S27°E 58.78' p.p. N74°E 80.71' tele. p.

Witness card No date Delamater-Muschell Engr. & Land Surveyors Cheboygan, MI Same witnesses & object as 1957-59 M.S.H.D. plans

10 11

12 13

Section A continued on back of this form.

\_\_\_\_ , Recorded Plat \_

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found boat spike in monument box and accepted as the best evidence of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Removed boat spike and replaced with 18" x 5/8" rod & 2" standard brass cap in concrete. Stamped cap G-13, T11N-R11E.

N47°43'W 58.15' chiseled "+" atop center of concrete headwall. N52°20'E 44.80' chiseled "+" atop center of concrete headwall.

S28°11'E 58.80' found M.S.H.D. tag in NE face p. pole. Also found p.k. nail & 2" disk

in SW face at 59.10'. S35°07'W 50.56' set T.C. Remon. tag & spike in NW face 15" pine. Also remains of OF MICHIGAN at 50.621.

Signed by \_

Date Aug. 1, 1994

LAND SURVEYOR

KENNETH D DUNTON

Surveyor's Michigan License No.

**APPROVED** 

20503-PROFESSION



## Section A continued:

May 19, 1982 Lapeer County Road Commission, Marlette Road corner witnesses, sheet 2 of 4. Found boat spike in monument box.

S45°E 59.12' set p. k. nail w/flasher in D. E. pole. S45°W 50.85' set p. k. nail w/flasher in 9" scotch pine. N45°E 51.51' set p. k. nail w/flasher in fence post.

