## 1995 REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE

For corners in Denmark	Filing Req	juirement of Act 74, Mich. P.A. 19	GERVED CERVED CERNO.
Tuscola (County)	Located In:	Corner Code ≠≠	
Public Land Survey	T <u>12N</u> R <u>7E</u> T R T R		FOR RECORD  PAGE HO  PAGE HO  APPR 3: 37  H. NICLARICH A COUNTY OF DEEDS
Property Controlling     in Section	S T R S T R		·*
Miscellaneous     Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
	Recorded Plat		A B C D E F G H I J K L M
o. Tivate damo			2 6 5 4 3 2 1 3
do hereby certify that under r in lines 1 and 2 above were current manual of survey ins Management or by a decree of above were in conformance of Court of Law; established, expressed below:	equirements of P.A. 74, Michigan in conformance with regulations tructions of the United States De of a Court of Law and/or that the civil the rules of the Michigan Boare-established, monumented,	P.A. of 1970, the corner points mentioned s and rules therefore as required in the epartment of the Interior, Bureau of Landorner points mentioned in lines 3, 4 and 5 and of Land Surveyors or by a Decree of a re-monumented, recovered, found as	4
NOTE: Not more than 4 on this certificate	•	n and range, may be recorded	12 31 32 33 34 35 36
A. Description of origina	I monument and accessories	and/or subsequent restoration:	13
June 26, 1971 Act 74 Form filed by David T. Rowe, R.L.S. Orange Risdon, D.S.  Set Post Corner of Sections 32 & 33  Beech 10" N75E 61 Links  Lynn 12" N37W 73 Links  Lynn 24" N8E 7 Links  September 26, 1978 Survey by David T. Rowe, R.L.S. #11192,  September 26, 1978 Survey by David T. Rowe, R.L.S. #11192,  recorded in Liber 1 Page 158, Tuscola County Records.  Same witnesses as Act 74 Form, Page 23 Denmark Twp.  September 26, 1978 Survey by David T. Rowe R.L.S. #11192,  recorded in Liber 491 Page 981 Tuscola County Records.  Same witnesses as Act 74 Form, Page 23 Denmark Twp.  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
below irons. Acce	pted "T" iron as the e G.L.O. notes relati	proper position of Corner	est. Found no other evidence E-13. The "T" iron falls 13, D-13, F-13 & G-13 along
	1. A		
	DEC :	1995	PAID)V
	COMM	ISSION	
C. Description of monum	ent for corner and accessorie	es established to perpetuate locating	g the position of the corner:
Removed "T" iron and placed concrete monument with standard brass cap stamped Corner E-13, T12N-R7E. Placed monument box over monument.			
S51°24'E 15.10' cer S61°47'W 20.33' set N06°59'W 23.05' set in S. face @ 22.7 N19°53'E 44.03' set N47°24'W 6.35' fnd. N17°50'E 96.95' SW	ter of 3" pipe (mail 1/2" x 18" re-rod i 5 T. C. Remon. tag & 74'). 5 T. C. Remon. tag &	box post). n road shoulder. spike in East face p. pole spike in West root 15" map at #8944.	e. (Fnd. nail & #11192 tag ple.  KENNETH D  DUNTON  SULTER
Surveyor's Michigan Licen	se No. 23503	APPROVED 9m4. FORM 1 10-23-95 gmg	APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

