1996 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in DENMARK TWP. Corner Code # Located in: TUSCOLA 1. Public Land Survey T 12N R 07E 2. Property Controlling in Section Register of Deeds Stamp & File Number 3. Miscellaneous S Т Property in Sec. ___, Recorded Plat 4. Lot No. CDEFGHI М В 5. Private Claims 2 1 6 3 4 7 8 0 ល 7.1 12 _ , in a field survey on <u>MAY_1.5</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land 13 15 14 6 . 18 17 16 7 9anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 23 24 8 0 วก 21 22 Court of Law; established, re-established, monumented, re-monumented, recovered, found as 9 25 10 30 29 28 27 26 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 32 12 31 33 34 35 36 13 A. Description of original monument and accessories and/or subsequent restoration: 1834 GLO; RISDON, D.S.; SET AS L-13 T13N-R7E; BEECH 12 N78W 37LKS, LYNN 10 N60E 39LKS 1974 ROWE, P.S.#11192; LCRC PG.27; SET ROD ON LINE BETWEEN NE & NW CORNERS & ON OCCUPIED LINES N & S; WAST 2641.80' ROD AT NE COR. SEC.1, NORTH 5.8' C/L PVMNT. E-W, S60E 42.50' N. END 6" CMP 1977 ROWE ENG.; DUNTON, P.S.#23503; SURVEY L.474, PG. 267; ROD; EAST 2641.80' ROD @ NE COR SEC.1, NORTH 5.8' C/L PVMNT E-W, SOUTH 208.10' ROWE TAG IN P/P 1984 LEDY ENG.; LEDY, P.S.#21575; SURVEY L.552, PG.1404; 1/2" BAR; S. 1.4' EDGE PVMT., N.23.2' ANGLE IRON, SE 42.60' TOP CTR 6" CMP NOTE: THIS CORNER IS COMMON WITH L-13 T13N-R7E Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1996 ROWE ENG.; FIELD, P.S. #37276; FND. 1/2" ROD 6.5' S. OF C/L ASPH. RD. E-W & IN LINE WITH FIELD DIVISION N-S. RECOVERED 2 PREVIOUS WITNESSES WHICH INDICATE THAT FND ROD IS IN SAME POSITION AS 1974 LCRC CITED ABOVE ACCEPTED FND. 1/2" ROD AS BEST EVIDENCE OF ORIGINAL CORNER POSITION Description of monument for corner and accessories established to perpetuate locating the position of the corner: REPLACED 1/2" ROD W/ STANDARD REMON MONUMENT STAMPED "L 13 T13N R7E" IN MON.: BOX N39°E, 23.29' SET 1/2" ROD W/CAP #37276 26.79' SET 1/2" ROD W/CAP #37276 N47°W, 24.40' SET 1/2" ROD W/CAP #37276 S77°W. 26.98' SET 1/2" ROD W/CAP #37276 S81°E, SO1°E, 207.95' FND. NAIL W/TAG #11192 IN N. FACE P.POLE JONATHAN M. FIELD **PROFESSIONAL** SURVEYOR No. Signed by Surveyor(s Michigan License No. 37276 App of Lan. FORM APPROVED BY MICHIGAN S ADAPTED FOR WORD PROCESSING M APPROVED

MAY 2 0 1997

CARBOAT C

HEMONUM

· Millianian

HOWE ENGINEERING ROPY

J,

