1996 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

HEER NO. CALLEGE 10. 65

For corners in GILFORI TUSCOLA (County)	O TWP. Located In:	Corner Code #	95 DEC 10 AM 8: 57
1. Public Land Survey	T <u>13N R 07E</u> T R T R T B	G-13	General Tropics Turchy a county The strike of breds
 Property Controlling in Section Miscellaneous Property in Sec. 	 _		Register of Deeds Stamp & File Number
	Recorded Plat	**	A B C D E F G H I J K L P

I, JONATHAN M. FIELD , in a field survey on MAY 15 19 96 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land 9anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

1	4 В (D D	E F C	9 H (JK	L M
2 :	6	5	4	3	2]
4	7	8	9	10	11	12
6	18	17	16	15	14	13
8	19	20	21	22	23	24
9 10	30	29	28	27	26	25
11 12 13	31	32	33	34	35	36
13						

- A. Description of original monument and accessories and/or subsequent restoration:
- 1834 GLO; RISDON, D.S.; SET POST; BEECH 4 N58E 43LKS, W OAK 14 N51W 1.80 CH
- 1974 ROWE, P.S.#11192; LCRC PG.14; SET 1/2" IRON 29.70' W OF NW COR SEC 3 T12N-R7E PER GLO NOTES; S70E 38.10' NE COR. BRIDGE ABUT., S45E 14.94' NW COR. BRIDGE ABUT., EAST, 29.70' NW COR. SEC.3 T12N-R7E
- 1977 LEACH ENG.; TOMMER, P.S.#22444; SURVEY OF NW 1/4 SEC.3 T12N-R7E; G-13 USED AS WITNESS OF WEST 29.70' FROM G-1 T12N-R7E

GLO NOTES FOR T12N-R7E INDICATE THAT THIS CORNER IS NOT COMMON WITH G-1 T12N-R7E

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1996 ROWE ENG.; FIELD, P.S.#37276; FND. 1/2" ROD 16' S. OF C/L ASPH. RD. E-W & ON C/L

EXTENDED OF APSH. RD. TO N. RECOVERED 1 PREVIOUS WITNESS WHICH INDICATES THAT FND ROD

IS IN SAME POSITION AS 1974 LCRC CITED ABOVE

ACCEPTED 1/2" ROD AS BEST EVIDENCE OF ORIGINAL CORNER POSITION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
G-13 REPLACED FND ROD W/ STANDARD REMON MONUMENT STAMPED "G 13 T13N R7E" IN MON. BOX

S12°E, 28.75' SET 1/2" ROD W/CAP #37276

N89°E, 29.70' FND. 3/8" ROD AT APPARENT G-1, T12N-R7E

N40°E, 83.50' SET P-K NAIL W/TAG #37276 IN SE FACE P.POLE

N34°W, 50.38' SET 1/2" ROD W/CAP #37276

Date 11-6-96

Surveyo('s Michigan License No. _37276

APPROVED 1800

JONATHAN M. FIELD PROFESSIONAL SURVEYOR No.

> RODAND OCH SURVEYOR JAN. 28, 197 OF E \$ 1 REVISED JAN., 1975 REVISED JAN., 1983 PTED PORTUGE VADCESSING MARCIK 1893

