## 1996 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE RECEIVED FOR RECORD Filing Requirement of Act 74, Mich. P.A. 1970

ME 110 Gillord For corners in GILFORD TWP. TUSCOLA 96 DEC 10 All 8: 56 Located In: Corner Code # (County) 1. Public Land Survey T\_13N\_R\_07E\_ TUSCOLA COURTY RECOUTER OF USERS 3N R 8E 2. Property Controlling in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. 4. Lot No. \_\_\_, Recorded Plat . CDEFGHIJKLM 5. Private Claims 1 2 2 1 3 I, JONATHAN M. FIELD \_\_, in a field survey on <u>MAY 17</u> 4 7 9 10 11 19 96 12 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land ó 18 17 16 15 14 13 9anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 19 8 20 21 22 23 24 Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: ò 10 30 29 28 27 25 26 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 31 32 33 34 35 36 13 Description of original monument and accessories and/or subsequent restoration: 1834 GLO; RISDON, D.S.; SET POST; SUGAR 14 S53W 41LKS, W MAPLE 14 N51W 41LKS 1971 ROWE ENG.; ROWE, P.S.#11192; SURVEY L.1,PG.321; FND 1" PIPE; N50W 84.10' BLDG COR STORE, N45E 52.54' NAIL & CAP IN P/P, WEST 2.5' C/L RD 1971 ROWE, P.S.#11192; LCRC PG.1; FND 1" PIPE; N50W 84.10' SE COR STORE, N35W 54.48' S. COR CONC BASE SIGN POST, N45E 52.54' NAIL & CAP IN P/P 1973 ROWE ENG.; ROWE, P.S.#11192; SURVEY L.433, PG.114; NO OBJECT STATED; NO WITS GIVEN GLO NOTES FOR TI3N-R8E INDICATE THAT THIS CORNER IS COMMON WITH A-11 T13N-R8E Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1996 ROWE ENG.; FIELD, P.S.#37276; FND. 1/2" ROD INSIDE 3/4" PIPE IN MON. BOX 4.5' S. OF C/L ASPH. ROAD E-W & 3'E. OF C/L ASPH. ROAD N-S. RECOVERED 2 PREVIOUS WITNESSES WHICH INDICATE THAT FND ROD IS IN SAME POSITION AS 1971 SURVEY CITED ABOVE. ACCEPTED FND. ROD IN PIPE AS BEST EVIDENCE OF ORIGINAL CORNER POSITION Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-11 REPLACED FND ROD IN PIPE W/ 5/8" ROD W/STANDARD REMON CAP STAMPED "M 11 T13N R7E" ENCASED IN CONC. IN MON. BOX S48°W, 30.96' SET 1/2" ROD W/CAP #37276 S41°E, 46.70' FND. NAIL IN SW FACE P.POLE N46°E, 43.04 CHIS. NOTCH IN TOP N. END 18 CMP N52°W, 79.19' NE CORNER OF BRICK ENCLOSED FORCH 84.22' SE CORNER OF BRICK ENCLOSED FORCH (1971 LCRC REFERANCE TO SE COR STORE) NS5°W. OF BILH Signed by MAHTAMOL M. FIELD Surveyor(s Michigan License No. <u>37276</u> E PACEESSIONALY . 1971 APPROVED SURVEYORE 11-4-96 OR WORD PROCE TOTAL TOTAL 37276 AOFESS

MAY 2 0 1007 Continues and con

 $\mathcal{Q}$ 

