1996 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

		LAND CORI	REMONUMENTATION PROGR. NER RECORDATION CERTIFI	am Cate		,	12	86		i so m
Filing Requirement of Act 74, Mich. P.A. 1970						8a \$7			5 2	E
For corners in WISNER	TWP.	Located In:	Corner Code #			nco Vicios	Serve Se	DEC 26 AM	Disoer	A BOS GBA
1. Public Land Survey		T_14N_R_07B_ TR TR TR	C-13			5053 7.153	5	Mi II: 49	Tup	Savos Savos
2. Property Controlling in Section 3. Miscellaneous Property is 0.	s	T R _ T R _ T R		Regist	er of D	eeds S	Stamp	& File	Numbe)r
Property in Sec. 4. Lot No, F. 5. Private Claims	Recorded	_ T R			A B	СЪ	E F	G Н	IJX	: L M
					6	5	4	3	2	1
do hereby certify that under	requirem	ents of P.A. 74. Michigan P	CEMBER 16 19 96 A. of 1970, the corner points mention	_, 4	7	8	9	10	11	12
current manual of survey ins Management or by a decree	e in confi structions of a Cour	ormance with regulations of the United States Depa t of Law and/or that the co	and rules therefore as required in artment of the Interior, Bureau of La	the 6	18	17	16	15	14	13
above were in conformance	with the i	rules of the Michigan Boar	d of Land Surveyors or by a Decree :	ofa 8	19	20	21	22	23	24

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

1	A B	C D	E F (G H	I J X	LM		
2	6	5	4	3	2	1		
4	7	8	9	10	11	12		
6	18	17	16	15	14	13		
8	19	20	21	22	23	24		
10 11	30	29	28	27	26	25		
12	31	32	33	34	35	36		

- Description of original monument and accessories and/or subsequent restoration:
- 1834 GLC; RISDON, D.S.; SET POST; ELM 12 N72E 22LKS, LYNN 20 N85W 41LKS
- 1917 BRUMLEY, MINUTES OF SURVEY FOR NORTHWEST DRAIN OUTLET NO.2; BK.26, PG.28 TUSCOLA CO. DRAIN NOTES; DRAIN COMMENCES 0.39 CH. S. & 0.25 CH. E. OF NW COR. SEC.5 T13N-R7E THENCE RUNS E'LY
- 1977 WITNESS CARD AT ROWE ENG.; 1" THREADED STUD IN NW BRIDGE WINGWALL; N35W 95.20' RLS TAG 11192 IN P.POLE, N80W 45.58' FACE OF ROAD SIGN POST, WEST 29' C/L GRAVEL N-S, SOUTH 17' C/L GRAVEL EAST NOTE ON CARD STATES "THIS MAY NOT BE THE SEC. CORNER"

GLO NOTES OF T13N-R7E INDICATE THAT THIS CORNER IS NOT COMMON WITH C-1 T13N-R7E

Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1996 ROWE ENG.; FIELD, P.S.#37276; FND 1" THREADED STUD IN NW BRIDGE WINGWALL; DID NOT ACCEPT AS PROPER POSITION FOR CORNER; REESTABLISHED CORNER POSITION BY SINGLE PRORATION OF GLO DIST. BETWEEN M-13 & E-13 T14N-R7E (21120' GLO VS. 21120.087 MEAS.) & ON LINE FROM B-13 TO D-13 T14N-R7E

POSITION FIT 1917 CALL TO C/L OF DRAIN W/IN 2-4'

ACCEPTED PROPATED POSITION AS PROPER REESTABLISHMENT OF ORIGINAL CORNER LOCATION

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-13 SET STANDARD REMON MONUMENT STAMPED "C 13 T14N R7E"

N21°E, 28.35' SET 1/2" ROD W/CAP #37276

49.29' SET CHIS. + ON CONC. WINGWALL N72°E,

N41°E, 65.85' FND. 1" THREADED ROD IN CONC. WINGWALL

N75°W, 12.24' SET NAIL W/TAG #37276 IN SE FACE 8" ASH

 $N02^{\circ}W$, 132.00' FND. NAIL W/TAG #11192 IN S. FACE P.POLE

OF MICH **NAHTANOL** M. FIELD PROFESSIONAL SURVEYOR No. 37278 ROFESSI

Signed by

12-24-96 Date

Surveyor's Michigan License No. 37276

m approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

\$ 15 P ほどの選

APPROVED 12-23-96

MAY 20 DAY

