Filing Requirement of Act 74, Mich. P.A. 1970

For corners in WISNER	TWP.		ement of Act 14, Wich. F.A. 157	J		10500 10500	٠	DEC 2		63759			
TUSCOLA (County)	<del></del>	Located In: .	Corner Code #			2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		ن م		10 20 20			
1. Public Land Survey		T_14N_R_07E_ TR TR	G-13			SES.	ξ°.	64:1143	1 1 mg	cond			
2. Property Controlling		TR	·										
in Section 3. Miscellaneous	Negister of Deeds Claim									& File Number			
Property in Sec.		TR	· · · · · · · · · · · · · · · · · · ·										
4. Lot No, Recorded Plat					A B (	D 1	E F G	; ;	J K	L M			
5. Private Claims				2	6	5	4	3	2	1			
L JONATHAN M. FIE	LD	. in a field survey on M	AY 21 19 96 .	3 4	7	8	9	10	11	12			
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					<u> </u>								
					18	17	16	15	14	13			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				7 8 0	19	20	21	22	23	24			
				10	30	29	28	27	26	25			
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					31	32	33	34	35	36			
				13	L	<u> </u>			I	! <u> </u>			

Description of original monument and accessories and/or subsequent restoration: 1834 GLO; RISDON, D.S.; SET POST; B. ASH 12 N34E 3LKS, B. ASH 14 N64W 27LKS 1902 FELTON, C.S.; SURVEY OF SEC.34, T14N-R7E PREV. SET CEDAR POST AND STONES. NO WITS GIVEN

GLO NOTES OF T13N-R7E INDICATE THAT THIS CORNER IS NOT COMMON WITH G-1 T13N-R7E

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1996 ROWE ENG.; FIELD, P.S.#37276; FND. NO EVIDENCE OF MONUMENT AT CORNER; REESTABLISHED POSITION FOR CORNER BY PRORATION TO 1902 FELTON SURVEY USING DIST. FROM G-12 TO G-11 T14N-R7E AND HOLDING LINE FROM G-12 THROUGH FND. NAIL AT OCCUPIED C/L OF AKRON ROAD CORNER POSITION FALLS IN STEEP DITCH BANK - SET WITNESS MONUMENT ON LINE G-13 TO G-12 T14N-R7E 19.04' N. OF G-13

ACCEPTED PROPORTION TO 1902 CO. SURVEY AS PROPER REESTABLISHMENT OF ORIGINAL CORNER POSITION

Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-13 SET WITNESS MONUMENT (STANDARD REMON MONUMENT STAMPED "W.C. G 13 T14N R7E" IN MON. BOX WITNESSES ARE TO WITNESS MONUMENT NOT CORNER G-13 (WITNESS CORNER)

N60°W, 25.29' SET 1/2" ROD W/CAP #37276

21.86' SET 1/2" ROD W/CAP #37276 S55°W,

\$28°E, 117.22' SET P-K NAIL W/TAG #37276 IN E. FACE P.POLE

71.64' SET P-K NAIL W/TAG #37276 IN NW FACE P.POLE N55°E,

N70°E, 39.12' SET P-K NAIL IN ASPH.

39.79' FND. NAIL IN ASPH. EAST,

Signed by Surveyor' Michigan License No. \_

REVISED MAY 14, 1975 REVISEO JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1993

OF MICH'S

JONATHAN

M. FIELD

POFESSY

ROFESSIONAL SURVEYOR No.

MAY 2 0 1997

TOTAL SALES STREET

V181

