1996 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

RECEIVEL	run hacono ,
Heta He	. PAGE 110. 84
instrol 🗟	PAGE 110. 84

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in S. AKRON TWP. 96 DEC 10 M1 8: 58 Corner Code # TUSCOLA _Located In: General Object 1. Public Land Survey T 14N R 08E_ 2. Property Controlling in Section Register of Deeds Stamp & File Number 3. Miscellaneous S Property in Sec. 4. Lot No. ____, Recorded Plat CDEFGHIJKL 5. Private Claims 2 Δ 6 5 3 8 12 JONATHAN M. FIELD in a field survey on MAY 21 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 6 17 16 15 14 13 current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 7 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 24 8 22 Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 25 10 29 27 26 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 31 32 33 36 13 Description of original monument and accessories and/or subsequent restoration: 1834 GLO; RISDON, D.S.; SET AS M-9 OF THE ORIGINAL GOVERNMENT SURVEY OF T14N-R7E; POST; W. OAK 16 N20W 14LKS, SYCAMORE 30 S46W 48 LKS 1902 FELTON, C.S.; PREV. SET POST, STONE AND CROCKERY; APPLE 3 S51E 1.21CHS, SUGAR 4 S25 1/4E 1.25LKS 1974 LEACH, P.S.#7236; LCRC PG.16; FND 1/2"x 3 1/2" IRON BAR; N85E 14.50' SW COR BRIDGE DECK N35E 31.30' NW COR BRIDGE DECK, S80W 71.10' BOLT IN E FACE P/P 1975 KAY, P.S.#14096; SURVEY L.449, PG.535; 3/8" ROD; N40E 29.03'BRIDGEPOST, S65E 27.77' BRIDGEPOST, S45W 44.67' RD SIGN POST, EAST 4.5' EDGE OF BLACKTOP 1985 DUNTON, P.S.#23503; SURVEY L.567, PG.577; SET R.R. SPIKE PER WITNESSES; SAME WITS AS 1974 LCRC ABOVE 1987 DE LA MATER, P.S.#13030; LCRC PG.16; FND. 3/8" BAR; P/P W/NAIL N45W 76.70', P/P W/NAIL \$55W 67.71', NW COR WINGWALL \$15W 27.41' 1995 ROWE ENG.; FIELD, P.S.#37276; SURVEY L.683, PG.10; FND. 2 1/2" PIPE IN MON BOX; N55W 76.58' FND ROOFING NAIL W/FLAG. NE FACE P/P, S50W 67.61' FND ROOFING NAIL W/FLAG. SE FACE P/P, N30E 30.86' SET CHIS "+" NLY COR NW WINGWALL, S30E 27.47' SET CHIS "+" SLY COR SW WINGWALL. GLO NOTES FOR T14N-R8E INDICATE THAT THIS CORNER IS COMMON WITH M-9 T14N-R7E Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1996 ROWE ENG.; FIELD, P.S.#37276; FND. 2 1/2" PIPE IN MON. BOX 10.5' E. OF C/L ASPH. ROAD N-S & 2' S. OF C/L GRAVEL ROAD E-W; RECOVERED 2 PREVIOUS WITNESSES WHICH INDICATE THAT FND. PIPE IS IN SAME POSITION AS 1975 SURVEY CITED ABOVE ACCEPTED FND. PIPE IN MON. BOX AS BEST EVIDENCE OF ORIGINAL CORNER POSITION Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-9 SET 5/8" ROD W/ STANDARD REMON CAP STAMPED "M 9 T14N R7E" INSIDE FAD. PIPE ENCASED BOTH IN CONC. IN MON. BOX N55°W, 76.58' SET NAIL W/REMON TAG IN NE FACE P.POLE S50°W, 67.61' SET NAIL W/REMON TAG IN SE FACE P.POLE 30.86' FND. CHIS "+" NLY COR NW WINGWALL N30°E, 27.47' FND. CHIS "+" SLY COR SW WINGWALL S30°E, 29.03' SW CORNER OF C-CHANNEL STEEL BRIDGE RAIL POST N55°E, 27.77' NW CORNER OF C-CHANNEL STEEL BRIDGE RAIL POST S65°E, ATHANCE.

SUPPLY S REPOSIMENTATION

Surveyor & Michigan License No. __37276

Signed by

11-27-96 2. F.E.

M. FIELD

PROFESSIONAL
SURVEYOR
ANALYTE BOARD OF AND SURVEYORS SA 28, 19
37270 REV SEMM 14, 197
ARAPTE OR WORD AND CESHNOL ARCH, 199

175

MAY 2 0 1997

SEC. 25
T14N-R7E

M-10

I80°12'30"

I834 GLO 2640'

A-10

VASSAR ROAD

SEC. 30
T14N-R8E

SEC. 24
T14N-R7E

I996 REI 2639.89'
I902 FELTON 2640'
I834 GLO 2640'

A-8

VASSAR ROAD

SEC. 19
T14N-R8E