jec 2 3 **200**0

RECEIVED FOR RECORD

PAGE NO. LIBERHO

1994 REMONUMENTATION PROGRAMFILING NO. #34

LAND CORNER RECORDATION CERTIFICATE EIKLAND TWP.

Filing Requirement of Act 74, Mich. P.A. 19784 NOV -9 PM 2: 15

For corners in ELKLAND TOWNSHIP YIRGINIA M. MCLAREN TUSCOLA COUNTY REGISTER OF DEEDS TUSCOLA Corner Code ≠# Located In: T14N R11E 1. Public Land Survey _ R. 2. Property Controlling S. in Section ___ T _ Miscellaneous S ____ R _ Register of Deeds Stamp & File Number Property in Sec. _ T ____ R ____

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

__ , Recorded Plat ___

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

expressed below:

5. Private Claims __

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

12

A. Description of original monument and accessories and/or subsequent restoration:

1835 (Gov't. Land Office Notes) Harvey Parke, D.S. -Set post corner Secs. 1 & 12 Hemlock 12 N12W 21; Hemlock 6 S8W 25

1888 (County Surveyor's Record, pages 80 and 81, Tuscola County) John A. Teskey, County Surveyor -Stake previously established- no accessories given,

1977 (Survey -Liber 475, page 336, Tuscola County) Stewart G. Case, P.S. 15399 -Fd. 1 iron pin in place-spike NW side P.P., N50°E-75.3!, spike in SE side T.P. -S45°W-45.12', center of steel Rd. sign post-N450W-41.65',

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner; Found 3/4" diameter 15" long smooth rod in monument box.

Accepted found rod as marking original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Removed 3/4" diameter rod and replaced with 5/8" diameter 15" long reinforcing rod with 2" Brass Cap stamped M3 T14N/R11E. Rod and cap set in concrete in monument box.

N50°E, 75.18'-T.C. Re-mon. tag in Northwest face of Power Pole.

S26°E, 38.43'-T.C. Re-mon. tag in Southwest face of 60" Box Elder.

S45°W, 45.08'-T.C. Re-mon. tag above found nail in Southeast face of Telephone Pole stub. N40°W, 37.15'-Exposed 3/4" diameter iron in top of leaning triangular concrete marker.

OF MICE

APPROVED.

Date ...

24593 OF WHO SHUNESON

LIONEL ROY EMERY LAND NO.

