FILED LAND CORNER RECORDATION CERTIFICATE 0V 15 2 52 PH 193 1993 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in COMMISSION VAN BUREN Corner Code ## Located In: 11/15 0101 10SURVEY SEC. 23, COLUMBIA TOWNSHIP N 1/4 CORNER, T <u>1S</u> R <u>15W</u> 1. Public Land Survey T _____ R __ __ R ___ R _ **Property Controlling** _ R __ T _ in Section Register of Deeds Stamp & File Number Τ. _ R _ Miscellaneous Property in Sec. ___ , Recorded Plat _ Private Claims _ , 19 93 -G.J. MITCHELL . , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: *SEE BACK OF SHEET* B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: DUG HOLE AT "T" FENCE POST LOCATION AND FOUND LARGE STONE APPROXIMATELY 2.5' DEEP. STONE WAS OVAL SHAPED (APPROX. 12" W X 24" L) WITH NO VISIBLE MARKINGS. "T" FENCE POST WAS SLANTED OVER CENTER OF STONE. SET STANDARD MONUMENT OVER FENCE POST AFTER ROAD CONSTRUCTION BY V.B.C.R.C. THIS GOVERNMENT MONUMENT WAS RESTORED WITH APPROVAL OF THE VAN BUREN COUNTY REMONUMENTATION PEER GROUP OF SURVEYORS, AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD MONUMENT

N 60° 161.91' -60d NAIL IN S. SIDE P. POLE -60d NAIL IN N. SIDE 10" PINE S 55° W 97.36'

N 70° Ε 160.78' -60d NAIL IN S. SIDE P. POLE

s 65° Ε 164.82 -60d NAIL IN N. SIDE P. POLE

OF MIC GEORGE J. MITCHELL PROFESSIONAL SURVEYOR No. 19618 OFESSION

Hovember 11,1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, REVISED MAY 14, 19

REVISEO JAN., 19

Liber 4 Pg. 73

Surveyor's Michigan License No.

NORTH QUARTER CORNER OF SECTION 23, TOWN 1 SOUTH, RANGE 15 WEST, COLUMBIA TOWNSHIP

GOVERNMENT - (1830)
SET 1/4 POST AT 40.50 CH = 2673.0'
6" BEECH - S 18 DEG W - 7 LKS.
14" BIRCH - N 83 DEG W - 13 LKS.

- A. J. PIERCE, CO SURVEYOR (3/11/70)
 WIT & STAKE GONE.
 S a TAMIRACK STAKE ON THE BI SECTION AT 40.225 CH = 2654.85'
 8" ELM N 73 DEG 30' E 70 LKS.
- T.A. SMITH, CO SURVEYOR (1946)

 FD LARGE STONE DROVE PIPE E SIDE OF STONE.

 DOUBLE 5" WAL N 5.9' TO CEN LINE

 15" MAPLE S 72 DEG W 80.0' TO CEN LINE.

 PIPE 6' N OF CEN LINE RD. & 6' E OF CEN LINE RD S.

 DIST TO NE CORNER = 2658.2'.
- W.Q.SMITH (8/29/73)
 FD "T" FENCE POST FROM OLD WIT & DIST TO NE CORNER = 2658.03'.
 WIT AS REC L2-P201.
- GOVE ASSOC (1990)

 FD CORNER FROM REC WIT.

 36" BASSWOOD N 30 DEG E 27.50' N & C.

 TRIPLE 18" BASSWOOD N 50 DEG W 72.80'.

 6" ELM N 10 DEG W 32.48'.

LIBER Y PAGE 74