Van Buren County Surveyor

NOV 1 5 1994

2' W CL Rd

P.P. - S 45° W - 64.07' Nails. Side Twin 8" CH - S 75° E - 64.57' Nail S side 6" Cedar - N 40° E - 64.99' Nail N side 10" Tree of Haven - S 55° W - 52.83' Nail NW side

Surveyor's Michigan License NDonald R. Gilchrist, RLS #13583

41	BER 4 PAGE 172 LAND CORN	IER RECORDATION CER	TIFICATECT 18 12 03 PH 194
	corners in Geneva Township	rement of Act 74, Mich.	
	Van Buren County Located in:	Corner Code ##	Mark a Snith &
1.	Public Land Survey T 1 SR16 W	8-E	EX
	E¼Post Sec 20 T R T R T R		10SUKWEY
2.	Property Controlling S T R in Section S T R		0101 10
3.	Miscellaneous S T R Property in Sec. S T R		Register of Deeds Stamp & File Number
	Lot No, Recorded Plat		он А В С D E F G H I J K 77
5.	Private Claims		
			3
	Donald R. Gilchrist survey on		4 7 8 9 10 11 1-1-1
	nereby certify that under requirements of P.A. 74, Michigan P.A	 of 1970, the corner points mer 	ntioned a l
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			
Cou	irt of Law; established, re-established, monumented, re- ressed below:		
-	TE: Not more than 4 corners, all in the same town a	and range, may be recorded	d 11
	on this certificate.		$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
A.	Description of original monument and accessories are	nd/or subsequent restoratio	
	Government - 1830 - Set 1/4 Pos A.J. Pierce, Co.Surveyor (3/23/		
	W.H. Goss, Co. Surveyor - (10/3 86° E- 27'	3004) - Fd stone	& crockery - 2½" Maple - N
	T.A. Smith, Co.Surveyor (9/24/4		
	D.R. Gilchrist, Co.Surveyor (10 Survey (8-164) P.P S 45	5° W - 62.26'; 8'	8, 11/28/78, 3/5/92). Rec " Twin Ch - S 80° E - 64.59";
	20" Maple - N 30° E - 126. G. Mitchell (1978) - Fd. re-bar		
В.	Description of corner evidence found and/or method	applied in restoring or rees	stablishing corner:
	Fd. 1/2" Iron (bent) Tied Off, ring.	Dug Down 1', Fou	und 1/2" pipe in cast iron
	Set 1' Section of Harrison Mark P.K. Nail - N 1.05	ker over top.	
	P.K. Nail - E 1.0		
	Corner was field checked on 9/2 Approved at the 10/5/94 Van Bur as a careful and faithful perpersonment Corner.	ren County Peer (Group Meeting and is accepted
C.	Description of monument for corner and accessories	established to perpetuate I	locating the position of the corner:
	Harrison Marker Iron 33' West		Ratified by Peer Group in accordance with P.A. 345 of 1998