
JAN 1 4 1998

## LAND CORNER RECORDATION CERTIFICATE DEC 16 12 00 PM 197

SECTION For corners in VAN BUREN COUNTY	Filing Requirement of Act 74  Located in: Corner ID #  GENEVA TWP. E 1/4 COR. SEC 13 T1S,R16W	Mark Charles Mark Charles Mark Charles
1. Public Land Survey	T_1S R_16W M-6  T R T R	
2. Property Controlling	STR	Liber 5 PAGE 50
in Section 3. Miscellaneous Property in Sec.	S T R S T R	Register of Deeds Stamp & File Numbe
4. Lot No,Records	ed Plat	ABCDEFGHIJKLM
5. Private Claims		2 6 5 4 3 2 1 1

I, Alan Bartlett in a field survey on December 2 1997 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

5/15/1827

WM. BROOKFIELD

NORTH ON EAST BOUNDARY OF SECTION 13

40.00 SET QUARTER SECTION POST

WITNESSES

**BEECH 13"** 

S751/2°W 22 LINKS

Ratified by Peer Group in accordance with P.A. 345 of 1998 Yan Buren County Surveyor

12/16/97

ALAN

BARTLETT

SURVEYOR

No. 35988

0 CAND

<del>7.00</del>

4/15/1952

NOTES SHOW 2606.2' NORTH TO NORTHEAST CORNER AND 2638.34' SOUTH TO SOUTHEAST CORNER NOTES SHOW ANGLE 89°54'30" FROM CENTER TO NORTHEAST CORNER. NOTES SHOW ANGLE 89°31'35" FROM SOUTHEAST CORNER TO CENTER

12/2/97

LANDMARK TECH. ALAN BARTLETT RLS #35988

FOUND 3/4" X 18" REBAR 2.0' WEST OF CENTER LINE OF COUNTY ROAD 681

WITNESSES

S70°E 38.87 \$10°€ 123.33 1"ANGLE IRON FLUSH WITH GROUND

SOUTH 25,59 43.53 S35°W

SET NAIL AND FLASHER IN 9" CEDAR WEST 1/4 OF SECTION 18 T1S,R15W

SET NAIL AND FLASHER IN 8" APPLE

33.69 N90°W

1" IRON PIPE W/CAP #2382

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4" REBAR IN PAVEMENT. VERIFIED CORNER LOCATION USING EXISTING WITNESSES.THIS GOVERNMENT MONUMENT WAS RESTORED WITH APPROVAL OF THE VAN BUREN COUNTY REMONUMENTATION PEER GROUP OF SURVEYORS NOVEMBER 19 1997.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 2 1/2 " HARRISON MONUMENT AND MONUMENT BOX 34.2" NORTH OF DRIVE EAST, 50.5" NORTH OF DRIVE WEST AND 2.0" WEST OF 2000 WITNESSES OF MICH

CENTER LINE OF COUNTY ROAD 681.

\$70°E 38.87 123.33

1" ANGLE IRON FLUSH WITH GROUND SET NAIL AND FLASHER IN 9" CEDAR

S10°E 25.59 SOUTH

WEST 1/4 CORNER OF SECTION 18 T1S,R15W

S35°W 43.53 N90°W 33.69

SET NAIL AND FLASHER IN 8" APPLE 1" IRON PIPE W/CAP #2382

CORNER IS ACCEPTED A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER

Date\_

12/15/97 12/10

Surveyor's Mich