MAY 1 6 1997

Van Buren

Van Buren County Remonumentation Program DEC 20

	-	_
Countricalan	LAND CORNER RECORDATION	CERTIFICATE
7.46-\$1.16	Filing Requirement of Act 74, Mid	ch. P.A. 1970

		Filing Requirement of Act				
for corners in Arlington	Township	Ouarter	Corner	22		

Located in:

,27

Corner Code #

1. Public Land Survey T2S R15W H9 Ratified by Peer Group in 2. Property Controlling Cordance with P.A. 345 of 1990 in Section Van Buren County Surveyor 3. Miscellaneous Property in Sec.

12/20 0101 10SURVEY Liber 4 Page 487 Register of Deeds Stamp & File Number

, Recorded Plat 5. Private Claims

I, <u>Gary C. Billow</u>, in a field survey on <u>5/28</u>, 19 <u>93</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A B	Ç	D	E į	, G	Н	I	J	ĸ	L J
2 - 6		_			ļ		Ţ		Ţ
3		_Ĭ_		, <u> </u>	ر آ		- <u> </u> -	1	1
4 - 7		- 8-		\Box	10		Ţ	1	
5		Ĭ	Γi	7			-11 -	\top	12—
		Ţ						1	1
7 18	\top		116	`	— I 5		-14 	1	1.3
8 _19.		20_						1	
9 1		-20-	ĺ	l		-	23 		24
					9	-			
10 30	_	29 <u>—</u> 	2E	-	27 	+	26 	 - 2	!5!
11]				7	1	1	
12 31-		32	—33 		-34 	\top	-35.— 	 	6

A. Description of original monument and accessories and/or subsequent restoration:

Post established by U.S. Deputy Surveyor G. Harrison in 1830 - accessories - Beech 22 S17E 21 links and Lynn (Basswood) 10 N33E 23 links. County Surveyor A.J. Pierce in 1869 recorded in Volume 3 Page 78 "Stake gone - accessories: 16" Lynn East 73." George Mitchell (PS #19618) reports on an unrecorded survey "Found 1" Iron pipe - accessories - SW 47.55' scaffold nail in 16" Ash, SE 49.00' 8" Ash, NNE 28.6' 10" Poplar, and South 4.0' centerline East-West road.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.
Found 1" Iron Pipe and three (3) of Mitchell's accessories. Distances to adjacent corners were reasonable and consistent. Accepted I' Iron pipe as the best evidence of the original post.

THIS GOVERNMENT MONUMENT WAS RESTORED WITH THE APPOVAL OF THE VAN BUREN COUNTY REMONUMENTAION PEER GROUP OF SURVEYORS AT A MEETING HELD SEPTEMBER 25, 1996, AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner Replaced 1" Iron Pipe with Harrison Monument on 12/19/96

S48°W 47.51' N16°E 28.01 4.0' South N20W 29.231

Scaffold nail in 16" Ash Face of 11" Poplar Centerline of 40th Avenue

Nail & Tag in Power Pole

OF MICHIG GARY C. BILOW Professional Surveyor No. 26453 POFESSIONA

26453 Surveyor's Michigan License No.

December 19,1996 Date