-SURVEY & REMONUMENTATION

JAN 1 4 1998

Van Buren County Remonumentation Program

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners in Covert Township Section Corner 24,25	51.50
	Van Buren Located In: Corner Code #	FileD
2. F ii 3. N	T_2SR 17W	DEC 1 4 34 PN '97 Mark a Smith VAN BUREN CO VAN BUREN C
4. L	_ot No, Recorded Plat	A B C D E F G H I J K L M
I,requestions	Gary C. Bilow , in a field survey on	ne 5
	overed, found as expressed below: TE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 29 28 27 26 25 11 13 31 32 33 34 35 36
А.	M9, Found rebar at surface 0.4 east of washing machine crank with stone around belobar in small mon box 40.18 south and 3/" pipe with remains of cap 48.93 south. Distart Accepted crank with stones around for corner location.	Survey, Surveyor AW Howard found an iron use, N45°E, 103.25; nail in W face 10" Maple, iron pipe, S, 48.84. In 1995 Surveyor DB Ratified by Feer Group in accordance with P.A. 345 of 1990 Van Buren County Surveyor corner: Date D. R. J. 12/11/27 Date OF THE VAN BUREN COUNTY
C.	REMONUMENTATION PEER GROUP OF SURVEYORS AT A MEETING HE AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL Description of monument for corner and accessories established to perpetuate locating the M9, Removed crank and set 20" Harrison monument in monument box in its place. When N34°W, 11.30, remains of PK nail(Zwar) S11°W, 40.18, 5/8" rod in small monument box N66°E, 103.18, SW corner house N42°E, 49.17, found nail in 20" Maple S18°E, 156.52, found nail in W face transformer pole S16°W, 112.33, NE edge hole in center of 30"diameter steel plate on N46°W, 113.29, found nail in SW face transformer pole	o position of the corner of Michigan Gary C. BILOW PROFESSIONAL SURVEYOR NO. 26453
	South, 48.93, Harrison monument at NW corner section 30, Bangor	Township
6	South, 48.93, Harrison monument at NW corner section 30, Bangor ligned by	November 19, 1997