JAN 1 4 1998

FILED

SECTION		Dec 17 2 or BU 107
NE cor., Sec. 12 LAN	D CORNER RECORDATION CERTIFICA	TE DEC 11 3 OH PM .3/
Paw Paw Township Van Buren (County) Filin Located In:	g Requirement of Act 74, Mich. P.A. 19 Corner Code #	DEC 17 3 O4 PH '97 Mark a Smith
7	R	Liber 5 Page 43 Register of Deeds Stamp & File Number
Property in Section S T	_ R	· · · · · · · · · · · · · · · · · · ·
4. Lot No, Recorded Plat	December 4 , 19 97 Michigan P.A. of 1970, the corner points mentioned lations and rules therefore as required in the current les Department of the Interior, Bureau of Land or that the corner points mentioned in lines 3, 4 and Michigan Board of Professional Surveyors or by a 1, monumented, re-monumented, recovered, found the town and range, may be recorded	A B C D E F G H J R 1
1827 - William Brookfield, D.S., "Set post corner", 9" Wh. Oak S. 16° 30' W. 51 lks., 14" Wh. Oak N. 41° 15' W. 19 lks 1910 - W.H. Goss, C.S., Stake, 10" Red Oak N. 37° W. 14', 12" Red Oak S. 76° W. 21.3', 16" Red Oak S. 36° W. 24.5', Jog is 2.80 chains (184.8') North of Antwerp corner. 1923 - T.A. Smith, C.S., Found pointed stone	1971 - T.A. Smith, C.S., Prepares "Marshall Peninsula" survey showing cor. as pipe, distance North to Antwerp corner is 184.8'. 1971 - W.Q. Smith, C.S., "Did not dig down to iron-used 60d spike as corner as used in previous survey. U.PSE39.30' to tack and washer, 30" Maple S.W. 59.18'	1972 - W.Q. Smith, C.S., "Found pipe-Set pipe over." 1972 - A.H. McMachen, R.L.S., Found railroad spike NW cor., HDWSW38.00', NW cor., HDWN.W39.75', NW cor., HDWN.E76.5'. 1976 - W.Q. Smith, R.L.S., Found railroad spike and witnesses same as in 1972

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

East of corner."

Found iron rod set in concrete matching the 1910 witnesse to 10" Oak (now 40"). Recovered (8) corners of the 1927 "Marshall Peninsula" survey which checked very well to found iron rod. Found iron rod was ratified by the Van Buren County Remonumentation Peer Group on August 27, 1997.

to tack and washer, Found 1" pipe 33'

Ratified by Peer Group in accordance with P.A. 345 of 1990 **Van Buren County Surveyor**

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found iron rod is accepted as the best available evidence of the position of the corner. Replaced found iron with a standard Van Buren County Remonumentation monument with mon box over, Accessories:

Nail in Northeasterly side of 40" Oak N. 35° W. 13.63' Nail in Northerly side of Twin 8" Cedar N. 85° E. 30.82' Nail in Northeasterly side of Utility Pole S. 55° E. 32.75' Southeast corner conc. block shed N. 75° W. 14.31'

7' West of centerline gravel road

Surveyor's Michigan License No.

and iron on Southwest side of stone-Set 60d

ALLEN H.

McMACHEN **PROFESSIONAL**

Surveyor

No.

16935

PROFESSIONAL

REVISED MAY 14, 1975 **REVISED JAN., 1983**