VAN BUREN COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

DEC 17 8 10 AH '96

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in HAMILTON TWP. Mark a Smith Van Buren Located In: Corner Code ## (County) T4 S. R __ 15 W. __ SUHVEY & 1. Public Land Survèv T _____ R ____ REMONUMENTATION W¼ Post Sec. 12 ____ R ____ T _____ R __ __ T ____ R ____ MAY 1 6 1997 2. Property Controlling S ____ T ____ R ____ S ____ T ____ R ____ S ___ T ____ R ____ in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. __ , Recorded Plat __ 4. Lot No. 5. Private Claims ___ John C. Hunt, P.S. December 11, 96 , in a field survey on . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:

1/1830 Gov.: E.Lytle DS: Ran N. bet. Sec. 11 & 12 a distance of 40 chs. & set quarter section post. Wit.: 10" white oak S57°W 24 lks. (15.84'), 12" white oak S43°E 77 lks. (50.82'). 8/15/1867 D.Lawton CS: Sections 11 & 12, Bk. 2 p.41, Same as N% post (statement) Good stone sunk at corner. Dist. N. is 39.75 chs. (2623.74'). 7/11/1972 E.Stefan RLS: Sec. 11 Recorded survey L2 p.208. Found railroad spike. Wit.: Pipe West 33', N60°E 54.05' face of 36" Oak, N85°W 16.8' to sign post. Distance North is 2635.6'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

West Quarter Post of Section 12, T4S-R15W, Hamilton Twp., Van Buren Co., MI.

Evidence found: Railroad spike. Removed and replaced with Harrison Marker in monument box.

Corner is 2' West of centerline of road North & South, in line with centerline of road to East and in line with fence line to West.

THIS GOVERNMENT MONUMENT WAS RESTORED WITH APPROVAL OF THE VAN BUREN COUNTY REMONUMENTATION PEER GROUP OF SURVEYORS AT A MEETING HELD ON JULY 31, 1996, AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 HARRISON MARKER IN MONUMENT BOX

N44°E 54.47' set nail & washer in Southerly base of 42" Oak tree. West 29.77' Set nail & washer in North face of wood fence corner post. S28°W 45.14' Set nail & washer in Easterly base of 26" Oak tree. S72°E 81.09' Set nail & washer in Northerly face of 34" Oak tree.

> Ratified by Peer Group in accordance with P.A. 345 of 1990 Van Buren County Surveyor

Date 12/16/96 D. R.

STATE OF MICHIGAN JOHN C.

HUNT
PROFESSIONAL
SURVEYOR
NO. 23513 SURVEYOR NO. 23513 AND SURVEYOR SURVEYOR

	,	
signed by John C. Hunt ps.	Date December 12, 1996	••••
Surveyor's Michigan License No23513	FORM APPROVED BY MICHIBAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19	

REVISED JAN., 1983