SURVEY & REMONUMENTATION

APR 2 5 1995

RC 1420

For comers in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LI27792PA277

Corner Code ## Located In: Wayne Dearborn Township #09 T 2S R 10E Compliance with G-11 1. Public Land Survey ACT 345, P.A. 1990 T _____ B ____ APPROVED ON: 12/6/94 DP-1 T _____ R _ T _____R _ WAYNE COUNTY REMONUMENTATION __ T _____ R __ PEER GROUP COMMITTEE 2. Property Controlling S ____ R __ in Section S ____ R _ 3. Miscellaneous Register of Deeds Stamp & File Number __ T ____ R __ Property in Sec. __ , Recorded Plat _ 5. Private Claims _ Lawrence R. ₁₉ 94 October 10 Feindt _ , in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

33 and 34, T 2 S, R 10 E G-11) Corner Common to Sections 27, 28, WAYNE COUNTY BUREAU OF TAXATION

GENERAL LAND OFFICE SET POST FOR CORNER BLACK ASH 12"-870 E-25 LINKS(16.50') BLACK ASH 10"-882 W-17 LINKS(11.22')

POINT SET IN M.H. COVER NE'LY-49.25'-TELEPHONE POLE SE'LY-88.55'-POWER POLE

SW'LY-46.85'-POWER POLE

15,00 MISUIL DYFOUR RETURNING 21 TEC 94 3 1/2 3/2 3 3 3 7 7 7 14 14

DECEMBER 24, 1816 BY: JOSEPH FLETCHER, DS

on this certificate.

NW'LY-47.35'-FIRE HYDRANT (SE HOSE CONNECTION) PORTAL S. V

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-11) Corner Common to Sections 27, 28, 33 and 34, T 2 S, R 10 E Manhole and one W.P.A. witness (fire hydrant) were found. No other direct evidence of corner was found. re-established from property corners found in "Dearborn Boulevard Subdivision" as recorded in Liber 39 of Plats, Page 56; and "Southland Subdivision" as recorded in Liber 41, Page 40. Distance to G-12 measured 2636.46' (WPA = 2637.32').



11 D-MISC

A. TOTAL OF THE PER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

G-11) 1/4 Corner Common to Sections 27, 28, 33 and 34, T 2 S, R 10 E Set four chisel marks on manhole rim intersecting at computed corner location at the intersection of Carlysle Avenue and Monroe Road. Road surface is asphalt. Actual corner falls on cover and cannot be set. The selected location is accepted by the contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Witnesses:

N51'E - 41.54' - Set nail & #21566 cap in NW face of power pole

44.75' - Set PK nail in North face of power pole and affixed Wayne County

brass disk stamped with licanse #21566

40.80' - Set nail & #21566 cap in East face of power pole

47.81' - SE hose connection on fire hydrant (WPA witness)

48.55' - Set chiseled "X" in top center of fire hydrant ___ Date ___ 12/21/ Rawsence R. Den W

Surveyor's Michigan License No. 21566