LAND CORNER RECORDATION CERTIFICATE RECEIVED Filing Requirement of Act 74, Mich. P.A. 1970 For corners in WEXFORD Located In: Corner Code # 1996 OCT -9 PH 3: 27 (County) Linka Loughmiller WEXFORD COUNTY, HI 1. Public Land Survey Т T т REGISTER OF DEEDS Ţ R 2. Property Controlling T Т in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section ___, Recorded Plat_ Private Claims CRAIG J. PULLEN _ , in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1838 ORIGINAL GLO SURVEY BY J. BRINK WOOD POST Y. PINE 13 N44E 17 W. PINE 14 N29W 25 1883 A.J. TEED SURVEY IN SEC.36, T23N, R9W MEASUREMENTS MADE TO CORNER. NO CORNER DESCRIPTION OR WITNESSES GIVEN. L-13 MICH. DEPT. OF CONSERVATION SURVEY IN SEC.1, T22N, R9W BY K. OSTLING, PS #10068 CORNER WAS ESTABLISHED BY PROPORTIONATE MEASUREMENT BETWEEN SECTION CORNERS. COULD FIND NO CONCLUSIVE EVIDENCE OF THE GOV. CORNER, ALTHOUGH A W. PINE STUMP TURN-OUT IS IN APPROXIMATELY THE RIGHT POSITION FROM OUR ESTABLISHED CORNER, FOR THE NW GOVERNMENT BT. SET 1" PIPE WITH BRASS CAP 6" R. OAK N36°E 10.60' 6" R. 1958 OAK S38°E 13,20 GRANGER ENGINEERING SURVEY IN SEC.1, T22N, R9W J. RAY, PS #25869 1" PIPE WITH BRASS CAP N36°E 10.60' 6" OAK 1979 S38°E 13.20' 6" OAK GRAND TRAVERSE SURVEYING CO. SURVEY IN SEC.1, T22N, R9W N. WAY, PS #28432 FOUND DNR MONUMENT WITNESSES SAME AS 1979 GRANGER SURVEY. Description of corner evidence found and/or method applied in restoring or reestablishing corner: L-13 FOUND 1" PIPE WITH BRASS DNR CAP IN GOOD CONDITION AND 2 PREVIOUS WITNESSES. THIS CORNER IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER. BY YEAR JO Peer Group Reviewed and Approved SEMONUMENTATIO 26 Sup 96 Willey - MAY 2 0 1997 Richard D. Wilcox, Wexford County Surveyor TO THE STATE OF TH C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

OF MICHIGA OF MICHIGA ER 9, 199 CRAIG J. **PULLEN** PROFESSIONAL 38095 SURVEYOR SEPTEMBER 9, 1996

Surveyor's Michigan License No. 4 PAGE 420 HDED

14 CORNER COMMON TO SECTION 36, T23N, R9W, AND SECTION 1, T22N, R9W

1" PIPE AND BRASS DNR CAP

RED OAK

RED OAK

RED OAK

RED OAK

9"

8"

14"

N36°E

S38°E

N2°F

S25°W 10"

Date

10.97'

13.76'

11.74

12.74'

39095