## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Wexford (County)		Located In				Corner Code	#									
1. Public Land Survey		T T	23N_	R R	10W	K5	_									
Property Controlling in Section	s	T . T		R R			_									
Miscellaneous     Property in Section	s s	T . T		R R			- -		Reg	jister (	of Deed	ds Stan	np & I	File N	lum	ber
4. Lot No:	Recorde	d Pla	at:					, A	вс	D E	F	GН	1	J K	L	M
5. Private Claims: _								2	6	_ 5	- -	3 3	-	2 -	  1 	_
I, <u>Craig W. McVean</u> , in a 1 requirements of PA 74, Min and 2 above were in conforthe current manual of sur Interior, Bureau of Land Macorner points mentioned in of the Michigan Board of established, re-established  NOTE: Not more than be recorded on this ce	chigan PA commance with vey instruction anagement of lines 3, 4 af Land Sur, monument 2 corners	of 197 n regulations or by nd 5 veyou ed, re	70, the oulations of the a decreabove version by ecovered	corne and Unite e of a vere i y a d, fou	er points rules the d States a Court o n confor Decree and as ex	mentioned in line refore as require s Department of f Law and/or that mance with the ri of a Court of Le pressed below:	es 1 d in the the ules .aw;	3	18 19 30 31 31			15		14		3
A. Description of origina	l monumei	nt an	d acce	ssori	es and/	or subsequent	restoratio	<sub>13</sub> ∟ n:	1 1		<u> </u>	_	L		l	
A. Description of origina  K-5 – <b>1852</b> – GLO Resu  1) Beech 16" S25	ırvey – Set °W 17 L.						- <b>1985</b> Fd. 1"	– LCRC " pipe in aple 8" S	inters	ectio	n road		s A. I	Ray		

- Old corner 3.90 Chs. East and 2.67 Chs. South, not agreeing with notes.
- **1899** CSR FB. 83, p. 20 W. S. Alderman Set stake and stone
- 1913 CSR Teed FB. 128, p. 27 & Teed card D. E. Teed --Found iron stake with stone around it. Shown to me by Bert Odell. Gov't wit. gone but he showed where Beech to NE stood which was alright. 3) Fence post 37 L. N & 45 L. W
- 4) Maple 10" S70°E 61.87'
- 5) Maple 48" S86°W 94.17'
- 6) Beech Clp. 4" N64°W 69.80'
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- K-5 Section Corner common to Sections 11, 12, 13 & 14, T23N, R10W Fd. 3/4" I.D. x 1.5'+ long iron pipe -0.5' below surface of gravel road per Ray. N-S centerline gravel road 1' east. Centerline gravel road east is 5.5' North. On line with centerline gravel road west. Witnesses #1, 2, 3, and 6 are gone. Fd. stp. for #7. Excavated 3/4" x 1.5'+ long pipe and find it is driven into 2" I.D. x 2.5' long iron pipe with ring of stones down 2'. 3/4" pipe in 2" pipe in ring of stone accepted as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K5 - Replaced pipes with 1 1/2" Wexford Co. Brass Cap on 5/8" x 34" rebar with 3" x 8" long PVC filled w/ concrete around cap -Down 0.6'. Left ring of stones in place.

S71°E 61.79' to set nail and tag in North side 20" Sugar Maple (#4) S30°E 45.99' to set nail and tag in Southwest side 14" White Pine S75°W 94.95' to set nail and tag in North side 56" Sugar Maple (#5) N26°W 50.69' to set nail and tag in Northeast side Fence Corner post N54°E 42.06' to set 1/2" x 18" iron rebar

Signed by: 39088 Surveyor's Michigan License/No.: