RECEIVED

JAN 1 7 1996

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1995 DEC 14 PH 3: 50

1:1. O

For corners in COMN	NISSION Films	nequirement (of Act 74, Mich. P.A. I	970	Jun	La i	(1) ³ (1)-05-1	o kanas	II.	٠,	
Wexford (County)	Located In:	Co	Corner Code ##		Linder Loughmiller MEXFORD COUNTY, MI REGISTER OF DEEDS						
Public Land Survey	T <u>23N</u> R T R T R T R		M-8		į						
2. Property Controlling	SR										
in Section	S T R										
3. Miscellaneous	S T R			Registe	r of D	eeds :	Stamp	& Fi	le Nu	mber	r
Property in Sec.	S T R							 -			
4. Lot No	Recorded Plat										
5. Private Claims					A B	C D	E F	G F	' '	J K	<u> </u>
				2	- -	├ ─ -	╅~	┼-┆	+	2	
		•		3	-	\vdash	╂╾╂╌	+-+		╁┼	
		<u>.</u>		4	7	↓ _	↓ ģ			╬┷┼	_ _ 2-
George D. Smith				. 6		1-1-	14-	11		igspace	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					 1 A	17-	 £-			凵	1
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					Ĭ	_ Ï] [J ï		ïΙ	ĩ
Management or by a decree of											Ţ
above were in conformance					—19— 	20-	21-	22	<u>'</u>	23-1	24-
Court of Law; established, re-established, monumented, re-monumented, recovered, found as						+ +-	+ +-	++	_	1 1	\dashv
expressed below:				10	—3¦o	29-	-2'8	2 7	/ - - :	26	25-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.						╂━┼┈	╁╼╁╾	+		++	
					-31	32	33	34	•——	35—	36
				13		<u>ــــــــــــــــــــــــــــــــــــ</u>				Ш.	
A. Description of origina	Il monument and access	sories and/or sub	sequent restoration:								
1966 USFS Notes b East 32.93', Maple 1	oy Griffen, PS# 13584, Fd 7" S 34° E 88.08' Cherry	l. Old Wagon Skei 1/2" S 36° W 61.0	or, Sugar 10 S 38°W 20 Su n, USGS Benchmark N 53 00' 318, Corner Fd, witnesses	3° E 75.84	4' , 1"		gn pos	sŧ			
B. Description of corner	evidence found and/or	method applied	in restoring or reestablis	hing con	ner:						

Found wagon skein as called for in 1981 record of Certificate of Survey by C. Cole PS #17615.

Found Wagon Skein as called for in 1981 C. Cole's Certificate of Survey Recorded in Liber 2, Page 318, did not accept position of Wagon Skein as corner position. Re-established 1/4 corner by single proportionate measure between found SE cor. Section 13 and the re-established SE cor. Section 36. This position is consistent with each 1/2 mile distance thruout entire township line. This corner is accepted as a careful and faithful re-establishment of the position of the original corner, being the 1/4 corner common to Section 24, T23N, R11W and Section 19, T23N, R10W.

Peer Group Reviewed and Approved

Richard D. Wilcox, Wexford County Surveyor

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron with Wexford County brass cap stamped: E 1/4 24, 1995, PS 39098, ±5' S'ly E'ly of North fence line N'ly. N 70° W 20.50' 30" Beech

S 45° W 11.83' 40" Maple N 42° E 31.33' 9" Scotch Pine N 6° E 20,30' 4" Ironwood

S 70° E 81.21' Wagon Skein West 70'± Centerline 2-trk (

Surveyor's Michigan License No

39098

APPROVED BY MICHIGAN SYATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

Gedarge+0

SMITH

PROFESSIONAL

No. 39098

POFESSIO

SURVEYOR

REVISED MAY 14, 1975 REVISED JAN., 1983