LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Wexford	Located In	Corner Code #	
(County)			
1. Public Land Survey	T <u>24N</u> R <u>9</u> T R	W L1	
Property Controlling in Section	S T R R		
Miscellaneous Property in Section	S T R R S T R R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G H I J K <u>L</u> M
5. Private Claims:			2 6 5 4 3 2 - 1
requirements of PA 74, Mic and 2 above were in confor the current manual of surv Interior, Bureau of Land Mar corner points mentioned in of the Michigan Board of	eld survey on Aug. 8, 2006 do higan PA of 1970, the corner p mance with regulations and rule eye instructions of the United spagement or by a decree of a Coines 3, 4 and 5 above were in colland Surveyors or by a Demonumented, recovered, found	oints mentioned in lines 1 es therefore as required in States Department of the ourt of Law and/or that the conformance with the rules cree of a Court of Law;	3 4
NOTE: Not more than 2 be recorded on this cer	2 corners, all in the same to tificate.	own and range, may	10 30 29 28 27 26 25 1 11 2 31 32 33 34 35 36 1
A. Description of original	monument and accessories	and/or subsequent restor	ration:
Fd. ¼ Post and put - 1912 – CSR – L. 1, E. P. Waterman 1" x 48" iron pipe ar 4) Elm 6" N57°W 70 1 ½' S. of straight lii - 1915 – C. P. Tuller E 40.02 to 'M13'; N 1957 – WCRC Rd.	/ 30 L. 65 L. p. 9 & 427 – G. T. Co. Rec. down Beech stake p. 495 & L. 5, p. 3 – G. T. Co nd cedar stake; 3) Sugar 14" 0.7'. Distance E & W is 2640 ne from Cor. to Cor. – Fd. iron corner.	- 1982 - pipe ra trail to 14" As o. Rec 9) \$20 - 1997 - G. T. 0 road ir Fence	ce Post S25°E 31.45'; 4) 27" Elm Stp. N55°W 70.03' - LCRC – L. 2, p. 492 – G. T. Co. Rec. – J. L. Wilcox – Fd. aised w/ spike 0.5' South of centerline. 15'E. of centerline North in fence line N & S. 5) S58°W 43.03' fd. nail in h; 8) N45°W 59.24' Fence Post; 10'E 32.20' fence post; 10) S66°E 67.96' - 3" Elm LCRC – L. 3, p. 742 and Rec. Sur. – L. 8, p. 430 – Co. Rec. – D. G. Heydlauff – Fd. large spike – 10' East of intersection; 5) S58°W 42.98' – Ash 20"; 11) S24°E 32.38' – Post; 10) S66°E 67.95' Elm 8"; 6) North 43.46' – P.P.
B. Description of corner	evidence found and/or metho	od applied in restoring or	re-establishing corner:
'U' x 2.2' long fence	e post iron and find 1" O.D. iron	on pipe per Waterman – l ⊦of 2-track N. is 15'± W.	R9W – Fd. 60D spike over 'U' fence post iron. Removed Down 2' – about 0.2' E. and 0.5' N. of fence post iron Traces of fence N & S. GLO & CSR Witnesses are gone. original corner.
C. Description of monum	nent for corner and accessor	ies established to perpetu	uate locating the position of the corner:
S54°W 43.71' to fd.	. Nail in NW side 28" Ash (#5 Nail in S. side Tw. 10" Elm (et N & T in E. side 12" Apple ½" CIR #28417	5)	cron pipe over fd. 1" iron pipe. Placed Mon. box. OF MICHIGAL CRAIG W. McVEAN PROFESSIONAL SURVEYOR No. 39088
Signed by: Surveyor's Michigan	License No.: 39088	Dem Date	A POST OCUDINAL SO