LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Wexford (County)	Located In	Corner Code #			
Public Land Survey	T 24N R 12W				
2. Property Controlling	T 24N R 12W	F10			
in Section	S T R S T R				
3. Miscellaneous	s				
Property in Section	S T R		Register of Deeds Stamp & File	Number	
4. Lot No:	Recorded Plat:		ABCDEFGHIJ	K L M	
5. Private Claims:			2 - 6 - 5 - 4 - 3 - 2 -	1-1-	
requirements of PA 74, Mi and 2 above were in confo the current manual of sul Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established	ield survey on <u>June 4</u> , 20 <u>08</u> do he chigan PA of 1970, the corner point ormance with regulations and rules the rovey instructions of the United Statemagement or by a decree of a Courtlines 3, 4 and 5 above were in configure of the Courtlines 1, 4 and 5 above were in configure or by a Decree 1, monumented, recovered, found as	ts mentioned in lines 1 herefore as required in tes Department of the tof Law and/or that the formance with the rules e of a Court of Law; expressed below:	3 4	13—	
NOTE: Not more than be recorded on this ce	2 corners, all in the same town ertificate.	n and range, may	10 30 23 27 26 11 12 31 32 33 34 35		
			13		
A. Description of origina	al monument and accessories an	d/or subsequent restoratio	n:		
Set gas pipe 1) Beech 22" S79 - 1979 – Unrecord K. L. Ross Fd. 1 ¼" pipe by E-W 2-track	. E. Sours, L. 2, p. 50 & 51. 9½°E 52 led Survey, Ross Surveys – File E. E. Sours, 1913, 6' South of co	E. E. No re # R-133 –	– CSR – L. 2, p. 108 Sours – E-W ¼ Line Road Survey eference to C ¼.		
3) 12" Red Pine 4) 10" Clump Ma 5) Concrete Mon B. Description of corner	ıple N40°E 49.40'		stablishing corner: Section 28 – Fd. 5/8" smooth iron rod	that is S76°42'E	
down 0.8' below groad 'T' intersection No evidence of #	, Section 29 – Found 1 72 O.D. I grade – 6' South of centerline of ion. Found witnesses #2, #3, & # 5. Accepted found 1 ½" O.D. iro idence of the position of the corn	E-W gravel 10.79 #4 intact. fence n pipe as no his er. used the co at into	or from the calculated intersection of ½ and tree line goes North ± from this instory on the origin of this 5/8" iron or the in any surveys. Thus I reject 5/8" smoorner and set stamped 2" Alum. Cap dersection of ¼ lines per Standard BLM south of centerline E-W 2-track Sand F	ines. Trace of ron. Could find that it had been both iron rod as on 5/8" x 34" rebard procedure.	
C. Description of monu	ment for corner and accessories	established to perpetuate	locating the position of the corner:		
D10 – 1 ½" Outside Diameter iron pipe N44°E 46.37' to found nail in Southeast side 13" Red Maple in a clump of 4 (¥4) N11°E 71.94' to set nail and tag at found nail in East side 20" Red Pine (#3) N57°W 47.01' to found nail in Northeast side twin 18" Cherry (#2) S17°W 30.76' to set nail and tag at found nail in East side 14" Elm Set Blue Carsonite Post with location tag 33' South		F10 - Stam Red Maple East side 18" Post S8°E East side S37° N28°	F10 – Stamped 2" Aluminum Cap on 5/8" x 34" rebar N77°41'09"W 84.67' to set ½" x 24" rebar for PI of centerline of E-W Road per 1916 Survey. North 48.00' to set 2" Alum. Cap on 5/8" x 34" rebar at intersection of N. Rd. ROW and ½ line with Blue Carsonite Post with loc. Tag. S8°E 33.06' to set N & T at fd. Nail in E. side 16" Red Pine S37°W 38.47' to set N & T in NW side 19" R. Pine N28°W 42.41' to set N & T in SE side 8" Spruce S76°42"E 10.79' to 5/8" iron rod		
Signed by: Surveyor's Michigan	My W. Mil	Ven_ Date:	1/14/2009	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR NO. 39068	
		FORM APPROVED BY MICHIO	GAN STATE BOARD OF PROFESSIONAL SUR	39088 AP ORS JAN 8 1971 ORS JAN 8 1971 ORS JAN 983 Reviser Ca. 1995	