SECTION

LAND CORNER RECORDATION CERTIFICATE

For	Corners in		rung	requirement of Act 14	, when	. P.A. 1970						
····	Washtenaw (County)	L	ocated In:	Corner Code	#							
1. [Public Land Survey	, <u> </u>	rı rı	R_4E		- Copy			94755			
3. N	Property Controlling 1 Section Miscellaneous Property in Sec.	s	r r	R	Haine		Co. co	REM L	se: 1 (1/07/20 3 P-31 Stamp	00 02:E		nber
4. 5	Lot No. Private Claim	Recorded Plat										
J.	Filvate Claim	<u>,</u>					V D (DE	F G	н ;	J H	К L м
							2 6	- 5	1	-3-	-2-	
do he in lin curre Mana abov	ereby certify that und les 1 and 2 above ent manual of survey agement or by a decr e were in conforman	were in conformance y instructions of the L ree of a Court of Law nee with the rules of the	A. 74, Miche with regulated State and/or that the Michigan with th	February nigan P.A. of 1970, the corner pulations and rules therefore as es Department of the Interior, the corner points mentioned in Board of Land Surveyors or bented, re-monumented, recovery	oints m require Bureau lines 3, y a Dec	entioned ed in the of Land, 4 and 5 cree of a bund as	4 7 7 5 6 18 19 9 9 10 30 30 19 10 10 30 19 10 10 10 10 10 10 10 10 10 10 10 10 10	- i	- 9	-15		
тои	E: Not more the on this certif		the sam	ne town and range, may be	reco		12 31	-32-	-33-	-34	_35_	-36-
A.	Description of o	riginal monument a	and acces	ssories and/or subsequent	restor	ation:	13			11		
	1825	J. Wampler GLO		Set Original Corner		6" Ash 10" While Oak	South N36E	4 lks. 16 lks.				
	07/29/1935	W.J. Armstrong Wash, Co. Road Co.	mm.	Found trace of old witness tre reset 1 ½" x 36" iron pipe with stones and bricks.		15" Ash 2" White Oak	N50W N05W	8.9' 31.4'				
	07/08/1971	Norman N. Fahrner #17620	LCRC L1P145	Found 1 1/2" iron pipe per occupation.	5) 6) 7) 8)	12" Oak 6" Oak 4" Basswood Angle Iron Fence Post	N20E S30W N45E N45E	19.8° 8.2° 0.7° 1.5°				
	04/25/1974	Washtenaw Eng. Job No. 11785 CCW #13604	Survey	Found fron pipe	9) 10) 11) 12)	18" Walnut	NO1E N56E S89W N62W	53.4' 63.8' 78.6' 71.2'				
	05/10/1979	Washtenaw Eng. Job No. 15948 NNF #17620	Survey	Found iron pipe	5) 6) 7) 8)	12" Oak 6" Oak 4" Basswood Steel Fence Posl	N20E S30W N45E N45W	19.8' 8.2' 0.7'				
	Continued on b	pack.			O)	Steet 1 chce rosi	144504	1.5'				
В.	Description of c	orner evidence fou	nd and/o	r method applied in restorii	ng or re	eestablishing co	orner:		APF	PROV	ÆD	. ha
į	Found 1 1/2" iron pip	pe with brick and stone	using acc	cessories 5,6,8,13,and 14.					DAT		ZZ	<u>/77</u>
c.	Description of m	nonument for corne	r and acc	cessories established to pe	rpetua	ite locating the	position (of the c	orner:		A	
				temonumentation Cap with Michor established as following:	nigan St	ate Plane Coordin	ate values	of North	312.02 E OF A	0.25 NCU	>	
	5)18" Oak 6)12" Hickory 8)3"x3" Iron Angle	N17E 20.1 S25W 8.3 N30W 1.4	1' Set	t P.K. Nail with Remonumentation P.K. Nail with Remonumentation			ļ		Street Street TIETO	OTHY	*****	

NO. 20712 NO. 20712 13)12" Elm 14) 12" & 4" Twin Elm Set P.K. Nail with Remonumentation Washer North side Set P.K. Nail with Remonumentation Washer North side Set P.K. Nail with Remonumentation Washer West side S65W 10.061 \$85W 14.96' S12E 23,091 Peer 2 2 von

Surveyor's Michigan License No. 20712

Continued from A.

07/20/1988	Craig Eckfeld #33135	LCRC L7P181	Found 1 1/2" iron pipe	5) 18" Hickory 6) 16" Hickory 8) Fence Post 13) 10" Elm 14) 10" & 4" Twin Elm	N20E S20W NW'iy S78W N84W	20,32' 8,14' 1,7' 9,95' 15,23'
08/16/1988	C. Wilson & Assoc. Job. No. 88224 A CAE #33135	Survey	Found 1 1/2" iron pipe	5) 18" Hickory 6) 16" Hickory 8) Fence Post 13) 10" Elm 14) 10" & 4" Twin Elm	N20E S20W NW'ly S78W N84W	20.32' 8.14' 1.7' 9.95' 15.23'
07/08/1992	C. Wilson & Assoc. Job, No. 92061 CAE #33135	Survey	Found 1 1/2" iron pipe	5) 18" Hickory 6) 16" Hickory 8) Fence Post 13) 10" Elm 14) 10" & 4" Twin Elm	N20E S20W NW'iy S78W N84W	20.32' 8.14' 1.7' 9.95' 15.23'
01/29/96	C. Wilson & Assoc, Job No. 95092 CCW #13604	Survey	Found 1 1/2" iron pipe	5) 24" Oak 6) 16" Oak 13) 16" Ash 14) 16" Ash 15) 20" Walnut	N'IY S10W S80W W'IY S20E	20.12' 8.35' 10.00' 15.00' 23.45'

Peggy M. Haines - Washtenaw Co. CORREM

5094755 Page: 2 of 2 02/07/2000 02:556

L-3 P-32

- Z000

SECTION

PAIR CO.