

**SURVEY & REMONUMENTATION**

MAY - 1 1995

**LAND CORNER RECORDATION CERTIFICATE**  
**COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Washtenaw  
 (County)

Located In:

Corner Code #

- 1. Public Land Survey T 1 S R 4 E L-11  
 T R  
 T R  
 T R
- 2. Property Controlling S T R  
 in Section S T R
- 3. Miscellaneous S T R  
 Property in Sec. S T R
- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

RECORDED  
 WASHTEENAW COUNTY, MI  
 Dec 1 11 28 AM '94  
 PEGGY M. HAINES  
 COUNTY CLERK/REGISTRAR  
 - COPY -  
 LIBER 1 PAGE 140 RM  
 Register of Deeds Stamp & File Number

I, R. Timothy Tietsema, in a field survey on December 10, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

- COPY -

|    | A  | B | C  | D | E  | F | G  | H | I  | J | K  | L | A |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |   |

**A. Description of original monument and accessories and/or subsequent restoration:**

| DATE   | SURVEYOR      | LS# | LCRC | SURVEY     | MONUMENT DESC.  | WITNESSES       |      |                   |
|--------|---------------|-----|------|------------|---|-----------------|------|-------------------|
| 1819   | GLO (Wampler) |     |      | Fld. Notes | Set Original Corner at average distance (39.87 chains to NE and NW Corner of Section 26). | 1) 8" B. Oak    | S74E | 54 links (35.64') |
|        |               |     |      |            |   | 2) 10" W. Oak   | N12E | 77 links (50.82') |
| 1930's | H. H. Atwell  |     |      | Resurvey   | Iron Pipe   | 3) 12" B. Oak   | Wly  | 37.0'             |
|        |               |     |      |            |   | 4) 28" Burr Oak | SEly | 65.0'             |
|        |               |     |      |            |   | 5) 5" Cherry    | NEly | 55.1'             |

**CONTINUED ON BACK**

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

In December of 1993, LSC found a 1/2" Iron rod using these witnesses:

|                   |               |      |       |
|-------------------|---------------|------|-------|
| Fnd 1/2" Iron Rod | 3) 28" B. Oak | N80W | 37.0' |
|                   | 4) 24" B. Oak | S23E | 64.6' |
|                   | 5) 12" Cherry | N30E | 55.0' |
|                   | 6) 17" Oak    | N56E | 30.0' |

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

|            |                |       |        |  |               |      |                       |
|------------|----------------|-------|--------|--|---------------|------|-----------------------|
| 12/10/1993 | R. T. Tietsema | 20712 | Remon. | Fnd 1/2" IR with a destroyed yellow cap. | 3) 34" B. Oak | N85W | 36.81' to nail & R.T. |
|            |                |       |        |  | 4) 48" B. Oak | S25E | 64.24' to nail & R.T. |
|            |                |       |        |  | 5) 18" Cherry | N30E | 54.80' to nail & R.T. |
|            |                |       |        |  | 6) 24" Oak    | N53E | 29.92' to nail & R.T. |
|            |                |       |        |  | 8) 10" Oak    | S80E | 26.30' to nail & R.T. |
|            |                |       |        |  | 9) 15" Oak    | S70E | 26.40' to nail & R.T. |

It is our opinion that this corner represents the original corner and is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by R. Timothy Tietsema Date October 3, 1994  
 Surveyor's Michigan License No. 20712

- COPY -

## CONTINUED FROM A. ON FRONT:

| DATE      | SURVEYOR  | LS#   | LCRC   | SURVEY     | MONUMENT DESC. | WITNESSES  |
|-----------|---|-------|--------|------------|----------------|--|
| Unknown   | W.C.R.C.  |       |        | Fld. Notes | Iron Rod       | 3) 12" B. Oak Wly 37.0'<br>4) 20" B. Oak SEly 65.0'<br>5) 5" Cherry NEly 55.1'   |
| 3/25/1977 | N. N. Fahrner<br>JOB NO: 14642                  | 17620 | LAP243 | Boundary   | Fnd Iron Rod   | 3) 28" B. Oak N80W 37.0'<br>4) 24" B. Oak S23E 64.6'<br>5) 12" Cherry N30E 55.0'<br>6) 17" Oak N56E 30.0'<br>7) 10" Hickory S79E 36.1' |
| 5/12/1978 | N. N. Fahrner<br>JOB NO: 15931                  | 17620 |        | Boundary   | Fnd 1/2" IR    | 3) 28" B. Oak N80W 37.0'<br>4) 24" B. Oak S23E 64.6'<br>5) 12" Cherry N30E 55.0'<br>6) 17" Oak N56E 30.0'<br>7) 10" Hickory S79E 36.1' |
| 6/10/1982 | R. Macomber<br>JOB NO: 34375                    | 27453 |        | Boundary   | Fnd 3/8" IR    | 3) 28" B. Oak N80W 37.0'<br>4) 24" B. Oak S23E 64.6'<br>5) 12" Cherry N30E 55.0'<br>6) 17" Oak N56E 30.0'<br>7) 10" Hickory S79E 36.1' |
| 4/4/1983  | N. N. Fahrner<br>JOB NO: 18589                  | 17620 |        | Boundary   | Fnd 1/2" IR    | 3) 28" B. Oak N80W 37.0'<br>4) 24" B. Oak S23E 64.6'<br>5) 12" Cherry N30E 55.0'<br>6) 17" Oak N56E 30.0'<br>7) 10" Hickory S79E 36.1' |
| 8/6/1985  | N. N. Fahrner<br>JOB NO: 20263<br>JOB NO: 21752 | 17620 |        | Boundary   | Fnd 1/2" IR    | 3) 28" B. Oak N80W 37.0'<br>4) 24" B. Oak S23E 64.6'<br>5) 12" Cherry N30E 55.0'<br>6) 17" Oak N56E 30.0'<br>7) 10" Hickory S79E 36.1' |
| 2/6/1986  | N. N. Fahrner<br>JOB NO: 20512                  | 17620 |        | Boundary   | Fnd 1/2" IR    | 3) 28" B. Oak N80W 37.0'<br>4) 24" B. Oak S23E 64.6'<br>5) 12" Cherry N30E 55.0'<br>6) 17" Oak N56E 30.0'<br>7) 10" Hickory S79E 36.1' |
| May 1991  | R. T. Tietsema<br>JOB NO: 01791                 | 20712 |        | Boundary   | Fnd 1/2" IR    | 3) 28" B. Oak N80W 37.0'<br>4) 24" B. Oak S23E 64.6'<br>5) 12" Cherry N30E 55.0'<br>6) 17" Oak N56E 30.0'<br>7) 10" Hickory S79E 36.1' |

APPROVED

DATE 1/25/94

CO. REP. KA