## SURVEY & REMONUMENTATION

MAY - 1 1995

	LAND CORNER RECORDATION		WASH
For corners in	Filing Requirement of Act 74, M	ich. P.A. 1970	TE HIER
	and the Common Condo white	ı	A CONTRACTOR A CON
WASHTENAW Locat	ed In: Corner Code ##	9	<b>∠</b>
1. Public Land Survey T 1	S R 5E   I-11		RUED COUNTY, II AGE 164 RM
	R	_	
	R	<del></del>	
	R	-	1 161 Dr
	R	_	IBER I PAGE 104 K/
	R	— Dominton of	ー C) Dグ ー Deeds Stamp & Fije/Number
	R	- Register of	Deeds Stamp & Wile Number
4. Lot No, Recorded Plat _			CDEFGHIJKLM
5. Private Claims		2 6-	5-4-3-2-1-1
		3	
		4 _ 7_	8 9 - 10 - 11 - 12 - 12
I. JOHN JEKABSON, in a field surve	y on 20 DECEMBER , ts	93 , 5	
do hereby certify that under requirements of P.A. in lines 1 and 2 above were in conformance wi			17-16-15-14-13
current manual of survey instructions of the Unit			
Management or by a decree of a Court of Law and	or that the corner points mentioned in line	es 3, 4 and 5 8	20 21 22 23 24
above were in conformance with the rules of the Court of Law; established, re-established, m			
expressed below:	onamentos, re menamentos, receivos	1030	29 28 27 26 25
NOTE: Not more than 4 corners, all in the	e same town and range, may be reco	orded 11	<del>                                     </del>
on this certificate.		1231	32 33 34 35 36
		13	
A. Description of original monument and a	•	ration:	
1819 G.L.O. Set Stake Wampler	W.O. 12		
·		n o-t-oor N oor	- aa am .
1932 25 June WASHTENAW CO. ROAD. COMM.	Found eye bolt 24" long in the center of a pile of stones. Reset with iron pipe		E. 69.65 1 W. 25.6 2
, W.J. ARMSTRONG #2444	and put 4 bricks around it.	Branching Elm 14" S. 15° E	i. 71.25 3
		2 R. of W. Pipes	
SEE BACK OF THIS SHEET (NEXT PAGE) FOR CONTINUATION OF SECTION "A"		·	
B. Description of corner evidence found a	nd/or method applied in restoring or	reestablishing corner:	
FOUND 3/4" IRON PIPE 0.4' BELOW ASPHALT SURFACE OF WEBSTER-CHURCH RD.			
USING 4 WITNESSES FROM SECTION "A"		,	•
None of Armstrong's witnesses still exist. Original			
Armstrong pipe may be at least 3 ft. under asphalt pavement. Note: distance to I-10 checks with Atwell-Hicks old records			
C. Description of monument for corner and	d accessories established to perpetu	ate locating the position	n of the corner:
Found 3/4" Iron Pipe 0.4' below asphalt surface of Webster-Church Rd	10" Basswood (PK & R.T. NE sd.) 13" Red Oak (PK & R.T. NW sd.)	N 45° W 43.85 N 40° E 58.98	8 5
	16" Ash (PK & R.T. NW sd.)	N 65° E 49.84	****
1994 AUGUST SET MONUMENT BOX WITH IRON & ALUM. REMON CAP	28" Red Oak (PK & R.T. N sd) 1/4 Cor. (I-10)	N 85° E 50.90 NORTH 2634,57	4 THE OF MICH, CALL
· • • • • • • • • • • • • • • • • • • •	1/4 Cor. (I-12)	SOUTH 2602.69	HAR STATE
	ì		* I. JOHN * 1
		م سا	PROFESSIONAL E
I conclude that after careful study of		,	SURVEYOR No.
this comer is accepted as the best availa	ble evidence of the position of the	onginai corner.	19836
O(100)			E O STATE
Signed by . July	nelson Dat	e12 Octobe	OFFECIONP AN
Surveyor's Michigan License No. 19836		12 00000	
		FORM APPROVED BY MICHIG	AN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

LIBER

## 1993 WASHTENAW COUNTY REMONUMENTATION PROGRAM

## I-11 (SECTION CORNER COMMON TO SECTIONS 26, 27, 34, & 35) WEBSTER TOWNSHIP TOWN 1 SOUTH, RANGE 5 EAST

History compiled by:
I. John Jekabson P.S. # 19836
Roskelly, Jekabson & Assoc. P.C.

											٤.۱	U.L.A	, "IL
1992 20 Aug.	1990 June	1988 1 March	1983 6 June	1982 3 March	1980 25 Aug.	1980 6 May	isoo i way	1977 9 June	1955 22 Dec.	1951 31 Dec.	1951 14 June	Old Records	DATE
ATWELL-HICKS INC.	LAND SURVEYING CONSULT R. TIMOTHY TIETSEMA Job # 08290-185E27	WASHTENAW ENG. CO. T.L. SUTHERLAND Job # 21795	WASHTENAW ENG. CO. NORMAN N. FAHRNER Job # 18677	WASHTENAW ENG. CO. NORMAN N. FAHRNER Job # 18168	WASHTENAW ENG. CO. NORMAN N. FAHRNER Job #17668	WASHTENAW ENG. CO. NORMAN N. FAHRNER Job # 17485	NOXWAN N. FAHRNER	ATWELL-HICKS, INC. JOHN L. SNYDER Job # 31683	ALTON D. SIMMS	DRURY, MCNAMEE & PORTER H.W. GOODWIN Job #1176	DRURY, McNAMEE & PORTER S.D. PORTER	ATWELL-HICKS, INC.	COMPANY SURVEYOR JOB#
1 A	ULT. #20712	#24620	#17620	#17620	#17620	#17620	#17620	#13352		#5434	#1469		P.S. #
							Liber 6, Page 7						P.A. 74 L.C.R.C.
S.E. 1/4 SEC 27	EAST 1/2 SEC. 27	East 1/2 SEC, 34	S.W. 1/4 SEC. 26	East 1/2 SEC. 34	S.E. 1/4 SEC, 27	EAST 1/2 SEC. 27		N.E. 1/4 SEC. 34	N.E. 1/4 SEC, 34	S.W. 1/4 SEC. 26	S.W. 1/4 SEC. 26	SEC. 27	LOCATION OF SURVEY
Found 3/4 Iron Pipe 0.4' below top of pavement Webster-Church Rd.	Found 3/4" Iron Pipe	Found 3/4" Iron Pipe	Found 3/4" Iron Pipe	Found 3/4" Iron Pipe	Found 3/4" Iron Pipe	Found 3/4" Iron Pipe	Found 3/4" Iron Pipe	Found 3/4" iron pipe .3 deep in C/L					MONUMENT DESCRIPTION
32" Red Oak %" Capped Iron Pipe 12" Red Oak 16" Ash	12" Oak to nail 24" Oak to nail 14" Ash to nail 10" Basswood to nail	Same as 1980, 1 May	Same as 1980, 1 May	Same as 1980, 1 May	Same as 1980, 1 May East 1/4 cor. Sec. 27	Same as 1980, 1 May	12" Oak to nail 24" Oak to nail 14" Ash to nail 10" Basswood to nail	30" R. Oak 12" W. Oak 8" Ash 12" Ash	None	None	West 1/4 cor. Sec. 26 (I-10)	East 1/4 cor. Sec. 27 (I-10)	WITNESSES
50,91 4. 33,02 9 58,96 5 49,82 7	N 40° E 58.98 5 N 85° E 50.90 4 N 65° E 49.84 7 N 45° W 43.85 8 (6?)				NORTH 2634.51		N 40° E 58.98 5 N 85° E 50.90 4 N 65° E 49.84 7 N 45° W 43.85 8 (6?)	N 85° E 51.0 4 N 50° E 58.8 5 N 55° W 43.9 6 N 70° E 49.8 7			NORTH	NORTH 2634 48	WITNESS ID
⊬ <b>P</b> ATE			-	i									COMMENT