



(CONTINUED FROM A. ON FRONT)

11/1844	G.L.O. HENRY PARKE	FIELD NOTES	NONE	1)	24" B. ASH N59 1/2°E 20 LINKS
				2)	18" B. ASH N61°W 26 LINKS
11/28/73	MIDWESTERN CONSULTING ALLEN RENTCHLER #15411	SURVEY 73103 & L.C.R.C. LIBER 3, PAGE 375	1" IRON PIPE	*4)	DRAINAGE DITCH EAST 23'
				5)	SPK NW SIDE 42" MAPLE N85°E 10.36
				6)	SPK. S/S 25" MAPLE N70°W 24.75
				7)	SPK. N/S 30" MAPLE S85°W 28.28
				8)	IRON PIPE 6' SOUTH & 25.8' EAST (USED AS E 1/4 COR. BY DETROIT EDISON FEBRUARY. '62
10/01/87	WASHTENAW ENGINEERING DOUGLAS MARSH	FIELD NOTES	SET 1 1/2" IRON PIPE	*9)	5" POPLAR NORTH 61.5 TO NAIL
				*10)	3" ELM N5°W 21.65 TO NAIL
				*11)	3" POPLAR S85°W 12.46 TO NAIL
				*12)	3" POPLAR WEST 7.86 TO NAIL
11/09/87	ATWELL-HICKS ROBERT MACOMBER #27453	SURVEY 503-197	1" IRON PIPE	*9)	4" DOGWOOD (NAIL) N10°E 6.16
				*10)	4" DOGWOOD (NAIL) N20°W 21.66
				12)	4" DOGWOOD (NAIL) N90°W 7.90
				13)	SET IRON N00°35'10"E 465.34
				*14)	SW CORNER SEC. 35 S00°35'10"W 2633.51

(CONTINUED FROM C ON FRONT)

- 15) RIGHT-OF-WAY FENCE  
SOUTHEASTERLY 27.6
- 16) NORTHEASTERLY END OF  
18" C.M.P. S60°W 26.02
- 17) NE CORNER CONCRETE HEADWALL  
N17°E 109.65
- 18) 18" TWIN MAPLE EAST 61.01  
TO WCRP TAG ON SOUTH SIDE

SURVEY &  
REMONUMENTATION

MAY 05 1997

COMMISSION