## SURVEY & REMONUMENTATION

MAY - 1 1995

Surveyor's Michigan License No. 19836



RECORDED WASHTENAW COUNTY, MI

Jan 10 9 49 AM \*95

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	•			PEGGY M. H	AIMES
WASHTENAW	Located In: (	Corner Code ##	1	COUNTY CLERK	REGISTER
(County)				-copy	/_
Public Land Survey	T2S R 3E	M - 13		CO. 1	'
				ส์ คลก	1000
			LIBER	1 PAGE 326	4 m
2. Property Controlling S	T	···		Copy -	
in Section S	T R			O .	
			Register of	Deeds Stamp & F	ile Number
Property in Sec. S	T R				
4. Lot No, Record	Jed Plat		А В	CDEFG	HIJK
5. Private Claims					
			3 1		1-1-2-1-
			, i		
I. I. JOHN JEKABSON , in a	field suprov on 21	October to 9/	, , , , , , , , , , , , , , , , , , ,	- <del> -</del> 8- -9- -1	0-11-
do hereby certify that under requirem	ents of P.A. 74. Michigan P.A. of 1970	the corner points me	antioned I I		
in lines 1 and 2 above were in confo	ormance with regulations and rules	therefore as require	ed in the	17	5-1-14
current manual of survey instructions				╼╂╌╁═╁═	
Management or by a decree of a Court above were in conformance with the r				20 21 2	2 23 -
Court of Law; established, re-esta	• • • • • • • • • • • • • • • • • • • •		01 1		
expressed below:			1030	29 28 2	726
NOTE: Not more than 4 corners	s, all in the same town and ran-	ge, may be recorde	ed 11		
on this certificate.	•		12 31-	32 33 3	35
			13		
	ment and accessories and/or su	bsequent restorati	on:		
1824 G.L.O SET POST JOHN M. MACK					
JOHN M. MACK			<b>5</b>		
1936 26 June WASHTENAW	Found old wood stake with a st	one beside it	B. Oak, 24" Cherry, 15"	N 37° E 37.1 N 88° E 36.4	1
COUNTY ROAD COMMISSION	Reset with 11/2" x 30" Iron Pipe	and placed 4 Bricks	Burr Oak, 36"	S 29° E 56.1	2 3
W.J. ARMSTRONG #2444	around it.		B. Oak, 36"	N 32° W 15.1	4
			Burr Oak, 16" 2 R. of W. Pipes	N 121/2°W 53.55	5
1972 9 May WASHTENAW ENG. C			211.0111.11pcs		6
NORMAN N. FAHRNER P.S. #17620 Act 74 L.C.R.C. Liber 1, Page 683	Found 1½" x 30" Iron Pipe		44" Burr Oak	S 29° E 56.1	3
about 1, 1 age cao			24" Hickory 50" Oak	E'LY 52.2 S 87° W 60.3	7 8
B. Description of corner evidence	ce found and/or method applied	in restoring or ree		001 11 00.5	Ø
			g		
FOUND 11/2" IRON PIPE AND BRICKS 2	OF RELOW ORANGE SUBSACE				
The second secon	DELOW GRAVEL GORFACE.				
USING 3 WITNESSES FROM SECTION	1 = A.7				
COMO O WITHESSES FROM SECTION	I A				
•			مٌ	.PPROVED	A.s.
				ATE 1/2/9	9
			C	O. REP.	
				4	
C. Description of monument for			locating the position	n of the corner:	
Favired 4478 Inc., 20	Spike & RT in NE sd 12" White Oak	N 30° W 43.0	05 9	*********	Maria
Found 1½" Iron Pipe and Bricks 20"	PK & RT in N sd 28" Shag Hickory	N 88° E 52.	.20 7	HANNE OF MIC	Y/O'N
below gravel surface. SET ½" X 18"	NW corner of House # 2435	\$ 50° E 159.	26 10	I. JOHN JEKABSO	14 32
IRON PIPE (with Remon Alum, Cap) in	PK & RT in SW sd 50" Burr Oak	\$ 29° E 56.	10 3	MHOL I	<b>₹</b> ★ <b>₹</b>
11/2" Iron Pipe 6" below gravel surface of	2 head nail in SE sd 7" Hickory	S 45° W 42.	66 11 🔮	JEKABSO	N \ \
Peckins Road	PK & RT in S sd in 50" White Oak	S 85° W 60.	30 8 <b>≨</b>	PROFESSION SURVEYOR	AL 15\$
	E. Face 4" Steel Fence Cor. Post	WEST 33.0	09 12	型 No.	AL BOAR
I conclude that after careful s	tudy of the record documental	tion and Eald at -	mations that	19836	12.5
this comer is a careful and faithfu	Il perpetuation of the position	ivii aliü ilelü opse of the original as	ervations, that	The Ap	Ce Me
		n are original corr	ICI .	A OFESSION	PART
	$\mathcal{I}$			ANTHONY SOL	44.

13 December, 1994