

SECTION

A. Continued

W.C.R.C., W.J. Armstrong # 2444, 3/19/33 Grid Book
Found pointed rock surrounded by smaller stones.
Reset with a 1 1/2"x 42" Iron pipe and put bricks and
stones around it.

- 3) 15" Hickory S8°E 63.0
- 4) 10" Elm S70 1/2°W 68.9
- 5) 4" Apple N40°W 36.9
- 6) 4" Maple N1°E 35.1
- 7) 40" Elm stump S40°E 42.0
- 8&9) 2 R. of W. Pipes

W.C.R.C., W.J. Armstrong # 2444, 11/43 Grid Book
(Knight Road Info)

- 3) 15" Hickory S8°W 62.4
- 4) 16" Elm S70 1/2°W 68.5
- 5) 4" Apple N40°W 36.7
- 6) 4" Maple N01°E 34.9
- 8&9) 2 R. of W. Pipes

Washtenaw Engineering, N.N. Fahrner #17620, 6/5/72
L.C.R.C., Liber 2, Page 211

R.R. Spike

- 3) 18" Hickory S8°W 63.0
- 6) 18" Hickory N8°E 35.3
- 10) 24' Box Elder N62°E 74.3
- 11) Utility Pole N4°E 29.5

C. Wilson and Associates, C.C. Wilson #13604
7/20/79, Survey 79146

R.R. Spike

- 3) 18" Hickory S8°W 63.0
- 6) 18" Hickory N8°E 35.3
- 10) 24' Box Elder N62°E 74.3
- 11) Utility Pole N4°E 29.5

Washtenaw Engineering, N.N. Fahrner #17620,
5/19/81, L.C.R.C., Liber 6, page 49; 5/29/81, Survey
R-4733; 5/11/83 Survey R-4956; 6/26/85, Survey
R-5258 - T.L. Sutherland #24620, 6/2/81, Survey
R-4735; 1/10/83, Survey R-5039; 5/5/83, Survey
R-4951 8/24/84, Survey R-5123

R.R. Spike

- 12) No Passing Sign N45°W 19.5
- 3) 18" Hickory S08°W 63.0
- 6) 18" Hickory N08°E 35.3
- 10) 18" Box Elder N62°E 74.3
- 11) Utility Pole N04°E 29.50 to Nail

Washtenaw Engineering, N.N. Fahrner #17620,
10/16/85, Survey R-5315

R.R. Spike

- 13) Power pole N60°E 103.25 to Nail
- 11) Power pole North 26.24 to Nail
- 14) Power pole N60°W 69.54 to Nail
- 12) Road Sign S45°W 19.50

Land Surveying Consultants, R.T. Tietsema #20712,
6/92, Survey 06692-2S5E34; 8/96, Survey 09596-
2S5E34

R.R. Spike

- 3) 18" Hickory S08°W 63.00
- 6) 18" Hickory N08°E 35.3
- 10) 24" Box Elder N62°E 74.8
- 11) Utility Pole N04°E 29.5

Washtenaw Engineering, T.L. Sutherland #24620,
5/9/95, Survey R-6912

Spike

- 3) 22" Hickory S08°W 63.00 to Nail
- 6) 22" Hickory N08°E 35.30 to P.K.
- 10) 24" Box Elder N62°E 74.30 to Nail
- 11) Utility Pole N04°E 29.24 to Flasher on W. Side
- 8) 2" Iron pipe South 32.85



Peggy M. Haines - Washtenaw Co. CORREM

5094727

Page: 2 of 2
02/07/2000 02:55P

L-2 P-326

- Copy -