I AND CORNER RECORDATION CERTIFICATE

			LAN. Fil	ing Requireme	nt of Act 74	, Mich. P.	A. 1970	SURVE'	Y &	
			111				REM	ONUME	NTATIO	NC
or con	ners in		1				!	NOV 08	1999	
<u>Wash</u>	tenaw (County)	Locat	ed In:	Corner Cod	e#			SECTIO	N	
	• • •		T 2S R 5E	K-2			- 2.	رود از از به المعامل م		
, Publ	ic Land Survey		T R T R T R						331 1 of 2 /1999 02: P-226	: 59P
	erty Controlling	S	TR	 .	Peggy M. Ha.	ines – Wasr 	Register of Dec	•		r
3. Mis	ection cellaneous perty in Section	s s	T R T R T R		Co	0.0.	D E F	G H I		L M
4. Lot	No,	Recorded Plat				A B C	, J G T	 		T
	ate Claims					2 - 6 +	- 5 + 4	+ 3 +	2 -	1 -
						3		10		12 -
I, The	omas L. Sutherlan	d , in a field surv	ey on , 11/21/9	98 do hereby state	that	4 - 7 -	- 8 9	10	11	12
under	r requirements of I	P.A. 74, Michiga d 2 shove were in	n P.A. of 1970, conformance	me corner points with regulations a	nd	5 - 18 -	- 17 - 1 6	+15+	-14-	13-
	therefore as required States Department	red in the current	manual of surv	yey instructions of	, the	7			- - -	+
4	a afa Court of La	w and/or that the	corner points	mentioned in time:	o -2', ¬	8 - 19 -	20 21	+ 22 +	- 23 -	- 24 - 1
Surv	s above were in co eyors or by a Deci	ce of a Court of	Law; establish	ed, re-established	•	9	- 29 - 28	+ 27	- 26	- 25
mon	umented, recovere	d, found as expre	essed below:			10 - 30 -	29 20	<u> </u>	-1-+	
						12 - 31 -	32 33	3 + 34 +	- 35 +	- 36 ·
	Description of original		nd accessories a	nd/or subsequent		13				!
•	G.L.O., 1815 Field 1) 27" WO S35° 2) 24" BO N30°	E 16 Links								
((Continued on oth	er side)	·							
В.	Description of come	r evidence found a	nd/or method ap	plied in restoring or	re-establishing	comer:				
	Found Bent 1" Iro fence line to the E stamped 24620.	n Pipe in North- ast. Reset 1" Iron	South Fence Li n Pipe with Alu	ne and 1.3 North o iminum Remonun	of Remnants on mentation Cap	:: ::				
c.	Description of mon	ument for comer a	ad accessories es	tablished to perpetu	ate locating the	position of the	e corner:			
	1" x 24" Iron Pipe 3) 14" Hickory	with Remonum S87°E 5.84 to I	entation Cap st Remon tag on I	amped 24620 North Side——						
	4) 12" Hickory 5) 18" Hickory 6) 18" Hickory 8) 3" Thoman	v S87°E 24.8 v South 14.65 to 1 v S85°W 21.64 to ble N15°E 6.80 to nce Post South 1.	Remon Tag on Remon Tag o Remon Tag o	E. Side n S: Side n East Side						
					· · · · · · · · · · · · · · · · · · ·		PRO DATE_ CO. REF	12-14-9	8_	
	I conclude that at is accepted as the	fier careful study best available ev	of the record d	ocumentation and ossiston of the original ocumentation of the original ocupanism of the original ocumentation of the original ocumentation of the ocumentation ocu	L.		is corner 21-98	$\mathbb{C}($)′
	Signed by:	hf.	Sille	SUTHERL	AND Date	12-	41.70			

Surveyor's Michigan License No. 24620

SURVEY & REMONUMENTATION

NOV 02 1999

SECTION

A. (Continued from Front)

W.C.R.C. W.J. Armstrong #2444, 10/20/36 Grid Book

- 3) Hickory 6" S87°E 6.05
- 4) Hickory 5" S87°E 25.2
- 5) Hickory 6" South 14.6
- 6) Hickory 8" S85°W 21.4



. ..

02/25/1999 02:59P CORREM L-2 P-227

Robert L. Smith #16052, 5-74, L.C.R.C. L3, P529 1" Iron Pipe at Anchor Post

- East 5.70 Nail in 10" Maple
- West 21.80 Nail in 18" Oak
- South 14.40 Nail in 15" Oak

Washtenaw Engineering, N. Fahrner #17620, 9/8/77, L.C.R.C. L4, P324; 9/13/77, Dwg. R-4006; 9/1/81, Dwg. R-4739 Iron Pipe

- 3) 12" Hickory S87°E 6.05
- 4) 8" Hickory S87°E 25.2
- 5) 12" Hickory South 14.66) 14" Hickory S85°W 21.4

Atwell-Hicks, R. Jagow Jr. 33137, Dwg 507-171 1" Iron Pipe

- 3) 14" Hickory Nail S. Side S87°E 6.05
- 4) 10" Hickory Nail S. Side S87°E 25.2
- 5) 14" Hickory Nail W. Side South 14.6
- 6) 18" Hickory Nail N. Side S85°W 21.4
- Centerline Fence Post for N-S-E Fence Line South 1.3