SURVEY & Filing Requirement of Act 74, Mich. P.A. 1970 REMONUMENTATION NOV 02 1999 or corners in Corner Code # Located In: Washtenaw SECTION M-2 T_2S_ R_5E . Public Land Survey _ R-02/25/1999 02:59P 2. Property Controlling in Section Register of Deed Stamp & File Number 3. Miscellaneous Property in Section Recorded Plat . 4. Lot No. . 1 5. Private Claims 2 3 11 12 4 5 18 16 6 I, Thomas L. Sutherland, in a field survey on November 4, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner 7 points mentioned in lines 1 and 2 above were in conformance with regulations 24 20 22 23 8 19 21 and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or 9 by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 25 29 28 27 26 30 10 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, 11

LAND CORNER RECORDATION CERTIFICATE

A. Description of original monument and accessories and/or subsequent resortation:

G.L.O. 1815 Field Notes

1) 9" Elm N2ºE 65 Links

monumented, recovered, found as expressed below:

(Continued on Other Side)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1/2" Iron Pipe 2.5 West of East edge of gravel, .5 below gravel surface inside, 2 1/2" Iron Pipe 1.2 below gravel surface surrounded by bricks and rocks 1.5 below gravel surface. Set Aluminum Remonumentation Cap stamped 24620 over 1/2" Iron Pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Remonumentation Cap stamped 24620 over 1/2" Iron Pipe (.5 below gravel surface and 2.5 West of East Edge gravel) over 2 1/2" Iron Pipe surrounded by bricks and rocks.

- 3) 12" Stump N65°E 16.48 to Spike on SE Side
- 5) Twin 12"-8" Hickory S51°W 45.88 to Remon Tag on E. Side
- 6) 24" Stump S56°W 34.38 to nail on SE Side
- 8) 26" Oak S35°E 32.16 to Remon Tag on SW Side
- 9) 16" Cherry N55°W 42.60 to Remon Tag on NE Side
- 10) 28" Ash N25°W 80.23 to Remon Tag on NE Side
- 11) A-2, T2S, R6E North 172.47

This Corner is not common to A-2, T2S, R6E.

I conclude that after careful study of the record documentation and field observations, that this corner

is accepted as the best available evidence of the position of the original corner.

Surveyor's Michigan License No.

THOMAS L. SUTHERLAND

No. 24620

CO LAND

12-21-98

34

33

32

31

12 13 35

36

A. (Continued from Front)

W.C.R.C., W.J. Armstrong #2444 9/10/36 Grid Book

Iron Pipe, Stones and Bricks

- 2) Elm 36" N23ºE 49.3
- 3) B. Cherry 4" N65°E 16.5
- 4) Forked Elm 6" S17°E 26.8 5) Twin Hickory 5" S51°W 45.9 6) Basswood 6" S56°W 34.4



copy-

Washtenaw Engineering, N. Fahrner #17620 12/21/76, Dwg. R-3854 and L.C.R.C. L4, P300 1/2" Iron Pipe

- 2) 36" Dead Elm N23ºE 49.3
- 3) 9" Cherry N65°E 16.5
- 5) 9" Twin Hickory S51°W 45.9 6) 24" Basswood S56°W 34.4
- 7) 20" Oak S45°E 9.5

Washtenaw Engineering, N. Fahrner #17620

11/10/78, L.C.R.C. L5, P149; 11/15/78 Dwg. R-4260; 11/16/78 Dwg. R4262; 3/31/79 Dwg. R-4347; 11/6/80 Dwg. R-4670

1/2" Iron Pipe

- 36" Dead Elm N23ºE 49.3 2)
- 9" Dead Cherry N65°E 16.5 3) 9" Twin Hickory S56°W 34.4
- 5&6) 20" Oak S45°E 9.5

SURVEY & REMONUMENTATION

NOV 02 1999

SECTION