MAY 0 9 1996

Miscellaneous

W.J. ARMSTRONG

LAND CORNER RECORDATION CERTIFICATE

| For corners in COMMISSION | | rining nequirement of Act 74, Mich. P.A. 1970 | | | 23 | LU 20 |
|---------------------------|-------------------------------------|---|----------------|-----------------|---|-------------|
| | WASHTENAW (County) | Located In: | Corner Code ## | b gr | *************************************** | ECOR NAW |
| 1. | Public Land Survey | T 38 R 4E | <u>A - 1</u> | WALEST WATER | 34 P | CED |
| | | T R T R | |) = 1 | ఆ | |
| 2. | Property Controlling S in Section S | T R | | | | |

Register of Deeds Stamp & File Number Property in Sec.

| 5. | Private Claims | | | | | |
|----|----------------|----------|-----|--|--|--|
| | • | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| 1 | | 24 0-1-6 | 0.4 | | | |

__ , Recorded Plat __

1. I. JOHN JEKABSON , in a field survey on ... 21 October 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: 24 G.L.O. - SET POST 1824

JOHN M. MACK 1936 26 June WASHTENAW Found old wood stake with a stone beside it. COUNTY ROAD COMMISSION

Reset with 11/2" x 30" Iron Pipe and placed 4 Bricks around it.

WASHTENAW ENG. CO. Found 11/3" x 30" Iron Pipe B. Oak, 24" N 37° E Cherry, 15" N 88° E 36.4 Burr Oak, 36" S 29° E 56.1 B. Oak, 36" N 32° W 15.1 Burr Oak, 16" N 121/2°W 53.55

10

12

2 R, of W. Pipes S 29° E 44" Burr Oak 56.1 24" Hickory E'LY 52.2 50" Oak 60.3

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 11/2" IRON PIPE AND BRICKS 20" BELOW GRAVEL SURFACE.

USING 3 WITNESSES FROM SECTION "A"

Surveyor's Michigan License No. 19836

1972 9 May WASHTENAW ENG. NORMAN N. FAHRNER P.S. # 17620

Act 74 L.C.R.C. Liber 1, Page 683

#2444

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Spike & RT in NE sd 12" White Oak N 30° W 43.05 9 Found 11/2" Iron Pipe and Bricks 20" N 88° E 52.20 PK & RT in N sd 28" Shag Hickory 7 NW corner of House # 2435 S 50° E 159.26 10 below gravel surface. SET 1/2" X 18" PK & RT in SW sd 50" Burr Oak S 29° E 56.10 3 IRON PIPE (with Remon Alum, Cap) in 2 head nail in SE sd 7" Hickory S 45° W 42.66 11 11/2" Iron Pipe 6" below gravel surface of PK & RT in S sd in 50" White Oak S 85° W 60.30 8 Peckins Road E. Face 4* Steel Fence Cor. Post WEST 33.09 12

I conclude that after careful study of the record documentation and field observations, that this corner is a careful and faithful perpetuation of the position of the original corner.

POPESSION 14 February, 1996

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, REVISED MAY 14.

STATE OF MICHIG

L JOHN

JEKABSON

UNIVEYO