

A. Paragraph A. Continued:

William J. Armstrong PS# 2444
 October 9, 1935
 30" Forked Elm S40deg.E 127.8
 28" Elm S36deg.E 125.0
 6" Elm S'y 116.7
 40" Forked Elm S45deg.W 26.0
 26" W. Oak N80deg.W 44.2
 20" S.W. Oak N75deg.W 30.3

Washtenaw Engineering Co., Inc.
 Norman N. Fahrner PS# 17620
 Act 74 Recordation, Liber 2, Page 271
 Found 1" Iron Pipe
 30" W. Oak N80deg.W 44.2
 26" S.W. Oak N75deg.W 30.3

Washtenaw County Road Commission
 Robert A. Campbell Jr. PS# 13028
 Act 74 Recordation, Liber 4, Page 171
 Found 1" Iron Pipe
 Rotted Stump N80deg.W 44.2
 Rotted Stump N75deg.W 30.3
 Wood Post Fences S'y & W'y North 9.5
 Fence S'y East 0.5
 6" Cherry North 10.23(Nail W/S)
 8" Poplar East 17.00(Nail N/S)
 5" Thorn Apple N75deg.W 34.79(Nail S/S)
 1/2" Iron Pipe W'y 940.5

C. Paragraph C. Continued:

RR Tie Fence Post N'y 9.20(Nail & RT W/S)
 Fence S'y East 0.5
 Leaning 8" Cherry N'y 10.18(Nail & RT W/S)
 8" Thorn Apple N75deg.W 34.42(Nail & RT S/S)
 1/2" Iron Pipe W'y 940.5
 8" Thorn Apple N75deg.W 14.04(Nail & RT E/S)
 6" Poplar E'y 23.33(Nail & RT S/S)
 6" Cherry S'y 7.93(Nail & RT W/S)

I find no evidence to conflict with the acceptance of this found corner as being a careful and faithful perpetuation of the position of the original corner.

This corner was ratified by the Washtenaw County Peer Committee on March 8, 1994

APPROVED

DATE 3/8/94CO. REP. KJ