SURVEY & REMONUMENTATION

MAR 0 9 1998

RECORDED #ASHTENAW COUNTY, MI

SECTION

Signed by

Surveyor's Michigan License No.

JAH 22 8 30 AM '98

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

				Filing Require	ement of Act 74,	Mich. P.A. 197	0 P	EGGY M. MAINE	4
For come	ers in						COUNT	ty clear then	ISTER
1 01 0011	-					•		- (00	· ·
	ashtenaw (county)		Locate	ed In	Corner	Code#		- cop	7
1. Public	Land Survey		T 4S	R_ 5E _	J.	-13			
	•		Ţ <u> </u>	₹				0 - 0	
			T 1	R				- COD	1
	rty Controlling	s		R				00000	randa da d
in Sec		S	<u>T</u> !	<u>R</u>	+		Libe	r UUUUUL	Page 0024 RN
3. Miscel		§	<u> </u>	₹ <u></u>			Panieta	or of Deeds Sta	mp & File Number
Prope	rty in Sec.	S	''		-		Negisie		-
4. Lot No		ecorded l	Plat				_ í	BCDE	FGHIJKLM
5. Private	e Claims	_					— ²	_ 6 5	╅╼┼╾┇╼┼╾┇╼┼╾┆╼
					•		3		
l, <u>R. Timo</u>	thy Tietsema		, in a field s	survey on	16 April	, <u>19 97</u>	_ 1	} -	9 - 10 - 11 - 12 - 12 - 1
					P.A. of 1970, the cor				
					rules therefore as re Interior, Bureau of			-1817	16-15-14-13-
by a decr	ee of a Court of I	Law and/o	or that the co	rner points ment	ioned in lines 3, 4,	and 5 above were	in 7		
					yors or by a Decre	e of a Court of La	w; 8	_19	2122
establishe	d, re-established,	monumer	itea, recovere	ea, tound as expre	essed below.		. 9		╀╌╀╼┼╾┼
NOTE:	Not more than	4 corner	s, all in the	same town an	id range, may be	recorded	10	3029	28-272625
	on this certificate.					"			
							12	32-	3336
A.	Description of o	riginal m	onument an	d accessories a	nd/or subsequent	restoration:	13		
11/29/1815	s Glo			Fld. Notes	Set Original Corner	1) 12" Beech	N54W	15 links (9.90')	Set Post for S 1/4 Corner
						2) 12" Lynn	S34E	41 links (27.06')	Section 35
3/31/58	Atwell-Hicks			Grid Book	Set 3/4" x20"	3) 12" Elm	N25W	24.7'	On fence line North & 24.5
	F.B. 598 P.24		•	& Fld. Notes	Iron Pipe	4) Tele. Pole	N40E	55.2'	North of fence on South side of road, 207.0' East to fence
									line South (Lenawee).
6 ID (1.05)		12750		Davidani	End Iron Dina	3) Elm Stump		24.7'	Fence line N'ly & E'Ly
5/3/1972	John Synder JOB NO, 27598	13352	L.1397 P.24	Boundary 4	Fnd. Iron Pipe	3) Eim Stump		24.7	20.0'
#10.11.0FA		12250		Davidami	End Ivan Dina	3) Elm Stump		24.7'	Fence line N'ly & E'Ly
7/3/1972	John Synder JOB NO. 27723	13352	L.1402 P.72	Boundary 5	Fnd, Iron Pipe	3) Euri Stump		27.7	20.0
10/0/1005	n m m .	00710		Boundary	Fnd. 1" Iron Pipe	5) Fower Pole	N87W	209.00'	
10/2/1995	R.T. Tietsema JOB NO. 10092	20712		Boundary	rad. 1 Hon Fipe	6) 8" Elm	N80E	83.79'	
						7) 6" Elm	EAST	140.15'	
В.	Description of c	orner evi	dence found	and/or method	applied in restori	ng or reestablishi	ng corn	er:	
In April of	1997 LSC found a 1	" Iron Pipe	from two previo	ous witnesses (5 & 6) and added two addition	onal witness (7 & 8).			
		•	•						
C.	Description of n	nonumen	t for corner	and accessorie	s established to po	erpetuate locating	the po	sition of the con	ner:
	Found 1	" Iron Pipe	and added Rem	onumentation Cap.					
	6) 8" Elm N80E 83.79' to P.K. & r/t							APPRO	<i>i</i> en
	7) 6" Elr 8) Utility			40.15' to P.K. & r/t 57.47' to P.K. & r/t				MALE (2/2/97
	, ,	GTE Riser							- / - (/ 1
	9) 5" Wi	nite Pine	N40E 4	14.72' to P.K. & r/t		•		CO. REP.	-
									-
It is our on	inion that this corner	represents t	he original cor	ner and is accented a	s the best available ev	idence of the position	of the ori	ginal corner.	

NO. 20712

20712

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

2 December 1997

Date