REMONUS	ABITATION .		<u>}</u>		
	LAND COAN	IER RECORDATION CE	1	SEP 21 II	RECORL .
WASHTENAW	Located In:	Corner Code ##	7	NAME 19	inu: 0±0
Public Land Survey	T <u>4S</u> R <u>6E</u> T R T R	K-11		AN '94 FOISTER	RLED COUNTY MI
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R S T R S T R S T R S T R		LIBE Register of D	1 PAGE COPY eeds Stamp & File	60RM e Number
	Recorded Plat		A B	CDEFGH	, I J K L
Patrick Hastings do hereby certify that under rein lines 1 and 2 above were incurrent manual of survey instributions and gement or by a decree of above were in conformance wi	, in a field survey on	ember 23 , 19 A. of 1970, the corner points mind rules therefore as requiritment of the interior, Burea per points mentioned in lines of Land Surveyors or by a De	nentioned 6 18—18—19—19—19—19—19—19—19—19—19—19—19—19—19—	8 — 9 — 10- 17 — 16 — 15- — 20 — 21 — 22- — 29 — 28 — 27-	23 - 2
NOTE: Not more than 4 con this certificate.	orners, all in the same town a	and range, may be record	ied 11 12 31	-32 -33 -34	35-3
A. Description of original	monument and accessories ar	nd/or subsequent restora			
1819	G.L.O. by Joseph Fro Beech 10" Ash 14"	ancis, D.S., Set pos S 22° E 15 1 S 31° W 23 1	ks		
No Date	W.C.R.C. gridbook by (1) N 02° W (2) N 34° W (3) S 63 1/2° W (4) S 76° W (5) N 24° W	Y H.H. Atwell. Iron         146.7' S.E. 6         68.6' 12" M         53.2' 30" M         93.8' 10" M         79.5' 10" M	corner of S. wing haple aple aple aple	ouse	
		CONTINUED ON BACK		·	
B. Description of corner e	vidence found and/or method	applied in restoring or re	establishing corner:		
1993 I:	found a 3/4" dia. solid occupied centerline located in a fill a excavate.	steel bar in a monun of Carpenter Road a rea for a bridge ove	nd Arkona Road exte	ended. This i	: the ,
	(15) S 30° E (17) N 20° E (18) S 70° W (19) N 64° W	86.63' 85.65' 92.23' 112.47'	Gas vent pipe 8" P.K. in guard rai P.K. in guard rai Gas pipe line mar yellow sig	l post. l post. ker, steel pos	
		CONTINUED ON BACK	<u>-</u>		
	nt for corner and accessories  ter a careful study of t		tion and field obse	rvation made u	inder my
	faithful reestablish	, I find this corne nment of the position tion cap stamped #37	n of the original c	orner. Set Wa	ashtenaw

Gas vent pipe 8", side center
RT & P.K. in guard rail post.
RT & P.K. in guard rail post.
Gas pipe line marker, steel post, yellow sign
N 1/4 cor. Section 36, T4S, R6E, 1" x 24" iron pipe
PROFESSIONAL
SURVEYOR

FORM APPROVED BY MINING STRIF BOARD OF LAND SURVEYORS JAN. 28, 191
REVISED JAN., 198 (15) (17) (18) (19) S 30° E N 20° E S 70° W N 64° W 86.63' 85.65' 92.23' 112.47' Easterly 2650.20

Signed by \_

Surveyor's Michigan License No. \_\_\_\_37277

## SECTION 'A' CONTINUED

No Dat	te		dbook second e	entry. Witnessed to chiseled "+" in pavement from A-H, Inc.
	(1) (2) (3) (4)	N 20° W N 34° W S 63° W S 76° W	146.25' 58.72' 53.60' 93.33'	S.E. corner of S. wing of house 20" Maple 36" Maple 18" Maple
	, <b>(5)</b>	N 24° W	79.77'	18" Maple
1934		W.C.R.C. gri Easterly		N 1/4 cor. section 35 (L-11)
1943		Survey by H. Southerly	H. Atwell, cor 2632.15'	rner shown on map. E 1/4 cor. section 35 (K-12)
1953				rner shown on map. E 1/4 cor. section 35 (K-12)
No Dat	e (1)	Witness from N 20° W	A-H, Inc. 146.25'	S.E. corner of S. wing of house
74	(2) (3)	N 34° W S 63° W	58.72' 53.60'	20" Maple 36" Maple
	(4)	S 76° W	93.33′	18" Maple
	(5) (6)	N 24° W S 70° E	79.77' 80.52'	18" Maple 22" Maple
1962		Survey by Atv N 01° 16' 15		c., found corner. 17' E 1/4 cor. Sec. 26 (K-10)
1967		Survey by N. N 01° 15′ 09	·	er shown on map. 67' E 1/4 cor. Sec. 26 (K-10)
1972	(7)	L.C.R.C. by 1 East	N.C. Jones, L. 1.37'	2, pg. 373, found 1* iron in concrete road. Center of Carpenter Road & Arkona Road to west
1973	(8)			.3, pg. 435, found 1" iron
	(9)	S 85° E S 30° W	21.79' 73.39'	N. leg of highway sign Sign post, "Pass with Care"
	(10) (11)	S 75° W N 30° W	48.81' 55.35'	N. leg of "Stop" sign S. end post of guard rail
1977		Survey by T.	Tietsoma, fou	nd no witnesses.
1990	(12)	Midwestern Co East	nsulting, four 21.08'	nd 1" steel rod Set P.K. in top of wood post for guard rail
		145¢		bee F.R. In cop of wood post for guard fair
	(13)	S 45° W	43.14'	Set P.K. in top of wood post for guard rail
	(13) (14)	N 45° W	35.26'	Set P.K. in top of wood post for guard rail
1992	(14)	N 45° W	35.26' A. Butterfield	Set P.K. in top of wood post for guard rail . Found 1" iron. Set 1" iron and mon. box
1992	(14) (8) (9)	N 45° W L.C.R.C. by A S 85° E S 30° W	35.26'  A. Butterfield 21.79' 73.39'	Set P.K. in top of wood post for guard rail  Found 1" iron. Set 1" iron and mon. box  N. leg of highway sign  Sign post, "Pass with Care"
1992	(14) (8) (9) (10) (11)	N 45° W L.C.R.C. by A S 85° E S 30° W S 75° W N 30° W	35.26' A. Butterfield 21.79'	Set P.K. in top of wood post for guard rail  . Found 1" iron. Set 1" iron and mon. box  N. leg of highway sign Sign post, "Pass with Care"  N. leg of "Stop" sign S. end post of guard rail
1992	(14) (8) (9) (10) (11) (15)	N 45° W L.C.R.C. by F S 85° E S 30° W S 75° W N 30° W S 30° E	35.26'  A. Butterfield 21.79' 73.39' 48.81' 55.35' 86.49'	Set P.K. in top of wood post for guard rail  . Found 1" iron. Set 1" iron and mon. box N. leg of highway sign Sign post, "Pass with Care" N. leg of "Stop" sign S. end post of guard rail "X" N. side gas vent
1992	(14) (8) (9) (10) (11) (15) (16) (17)	N 45° W L.C.R.C. by F S 85° E S 30° W S 75° W N 30° W S 30° E S 48° E N 20° E	35.26' A. Butterfield 21.79' 73.39' 48.81' 55.35' 86.49' 28.65' 85.65'	Set P.K. in top of wood post for guard rail  . Found 1" iron. Set 1" iron and mon. box N. leg of highway sign Sign post, "Pass with Care" N. leg of "Stop" sign S. end post of guard rail "X" N. side gas vent P.K. in guard rail post P.K. in guard rail post
1992	(14) (8) (9) (10) (11) (15) (16)	N 45° W L.C.R.C. by F S 85° E S 30° W S 75° W N 30° W S 30° E S 48° E	35.26'  A. Butterfield 21.79' 73.39' 48.81' 55.35' 86.49' 28.65'	Set P.K. in top of wood post for guard rail  . Found 1" iron. Set 1" iron and mon. box N. leg of highway sign Sign post, "Pass with Care" N. leg of "Stop" sign S. end post of guard rail "X" N. side gas vent P.K. in guard rail post

## SECTION 'B' CONTINUED

Measurement comparison from K-11 to:

Corner	Company	<u>Year</u>	Distance
K-10	G.L.O.	1819	2640.01
	A-H. Inc.	1962	2648.47'
	Wash. Eng. Inc.	1967	2649.57'
	M.C.I.	1993	2648.49'
K-12	G.L.O.	1819	2640.0' = 40 CH
	H.H.A.	1943	2632.15'
	H.H.A.	1953	2632.64'
	M.C.I.	1993	2633.00'
L-11	G.L.O.	1819	2656.50', 40.25 CH
	W.J.A.	1934	2660.0'
	M.C.I.	1990	2650.18'
	M.C.I.	1993	2650.20'
J-11	G.L.O.	1819	2640.0' = 40 CH
	A-H	1962	2563.65'
	M.C.I.		2562.94'

APPROVED
DATE 4/5/94
20. REP. M