SUFVEY & REMONUMENTATION

MAY - 1.1995

4. Lot No. .

5. Private Claims __

LAND CORNER RECORDATION CERTIFICATE

____ , Recorded Plat .

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

_	INGO.	Ť,	≯
	NE .	<u></u>	ASHTENAW COUNTY. HI
ŗ	05		ZÃ
O	ME	********	₹ 5
O.	\$ E	2	3G
X	őz		= =
	REGISTER		-<
	땠	É	- 125

Fo	r corners in			
	WASHTENAW (County)	Located In:	Corner Code ##	ARES L PER
1.	Public Land Survey	T <u>4S</u> R <u>6E</u> T R	M-12	
	-	T R T R		LIBER 1 PAGE 78RM
2.	Property Controlling in Section	\$ T R \$ T R		-COPY-
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

, Patrick Hastings, in a field survey on December 27 . 19 93 .
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
a variable of his control of the con

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 11
- A. Description of original monument and accessories and/or subsequent restoration:
 - 1815. G.L.O. Township boundary by Set a beech 18 N7E 11, a Beech 18 N67W 15 1.
 - a peech 18 N/E 11, a Beech 18 N6/W 15

 1934. W.C.R.C. W.J. Armstrong, Found the marks of 2 old wood stakes about 6" apart.

 Reset with a 1 1/2" x 42" iron pipe and put 4 bricks around it. Mar. 8, 1934:

 Catalpa 14" N 69° E 19.8'

 N.W. Cor. House N 69° E. 59.7'

 Maple 12" S 32° E 5.9'

 Maple 12" S 32° E 5.9'

Maple 14" S 0 1/2° W 29.3'

- 1969. N.N. Fahrner, Washtenaw Engineering, used corner in survey, no witnesses.
- , Atwell-Hicks, Inc. used corner in survey, no witnesses.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/4" iron pipe with brick around it 12" \pm below surface, that is raised with 3/4" iron pipe 4" below surface. From remaining witnesses,

N 3° E 19.8' - Now blown over S 32° E 5.9' S 1/2° W 29.3' Catalpa 30" Maple 24" Maple 24"

> APPROVED DATE 1/25/94 CO. REP. K

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

After a careful study of the record documentation and field observations, made under my direct supervision, I find this corner as remonumented to be the best available evidence of the supervision, I find this corner position of the original corner.

Set standard remonumentation cap stamped #37277 on existing 3/4" iron pipe 4" below grade in top of 1 1/4" iron pipe surrounded with bricks. MICHICAL

S 32° E 5.90' S 1/2° W 29.30' N 45° W 1.70' North 19.5'±

24" Maple, set P.K. in west face
24" Maple, set P.K. in east face
R.R. tie fence post, set P.K. in south face
Fence line West
Fence line East

Date .

South 178.0'+

372

Signed by __;

HASTINGS PROFESSIONAL SURVEYOR

*

FORM APPROVED BY MICHIBAN STATE BURND OF LAND SURVEYORS JAN. 28, 1971
REPORT MAY 14, 1975

PATRICK L.

Surveyor's Michigan License No. _