MAY - 1 1995



FEB | 8 59 M '95

RECORDED

WASHTERAW COUNTY, MI

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION For corners in

5. Private Claims \_

Filing Requirement of Act 74, Mich. P.A. 1970

PEGGY M. HAIRES

Washtenaw (County)	Located In:	Corner Code ##	- COP	
Public Land Survey	T R T R	<u>K-10</u>		:
	T R T R		# 00f	2.0
Property Controlling     in Section	S		LIBER 1 PAGE 385	KM
Miscellaneous     Property in Sec.	S T R S T R	-	Register of Deeds Stamp & File Number	
4. Lot No,	Recorded Plat			

Thomas L. Sutherland in a field survey on \_\_ November 14 . 19 \_\_.94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(W.C.R.C. 1932) Found an old wood stake and a square boat spike 20" long surrounded by bricks and re-set with a 2" x 48" Iron Pipe and put 4 bricks around 2 Right-of-Way Pipes

(Midwestern Consulting 1992) Nail in Iron Spike N/S U.P. N88°W 28.25 PK S/S 6" Oak EAST 35.75

(Glen Richard 1992) 3/4" Iron Pipe Double head Nail in E. Pole S20°W 115.20

(Atwell-Hicks 1993) 3/4" Iron Pipe Utility Pole S15°E 115.18 to Nail Utility Pole N81°W 27.86 to Nail Utility Pole N75°E 63.92 to Nail Fiber Optic Marker N28°W 72.26 to N.R. Face

11

12

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" Iron Pipe 4" below gravel surface with bricks 12" below gravel surface. There was no other pipe below the 3/4" Iron Pipe. Se Set Aluminum Washtenaw County Remonumentation Cap on existing Iron Pipe and adjusted to 6" below gravel surface.

> APPROVED DATE 11/21/94 CO. REP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

\*

3/4" Iron Pipe with Aluminum Washtenaw County Remonumentation Cap

6" below Gravel Surface 2" Iron Pipe WEST 33.00 Utility Pole N85°W 27.70 to Nail W/W.C.R. Tag in

N. Side Utility Pole S15°E 115.20 to Nail W/W.C.R. Tag in E. Side

Utility Pole N75°E 63.95 to Nail W/W.C.R. Tag in N.Side Fiber Optic Marker N35°W

ber Optic Marker Noo w 72.22 to Nail W/W.C.R.Tag in NE Side

10" Poplar N35°E 37.40 to Nail W.W.C.R. Tag in NW Side Fiber Optic Marker S80°E 47.42 to Nail W/W.C.R. Tag in S Side

I conclude that after careful study of the record documentation and field observation, that this corner is accepted as the best available evidence of the position of the original corner.

GEOTHERAMO

Date\_ 21620 2157 

December 14, 1994

The Seth Thomas L. Sutherland Surveyor's Michigan License No. ‡24620

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983