## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 47 NR 16-174

		Alger
DESCRIPTION	OF CORNER	1/4 Cor. between Secs: 24-19
DESCRIPTION (	OF CORNER	MONUMENT 1" Pipe with 4" Brass Cap
WITNESSES T	O CORNER .	9" H. Maple (1/4s NBT) S13°E 8 Lks.
		12" H. Maple (1/4s NBT) N77°E 41½ Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Cor. from Sugar B.T. bearing S44°W 50 Lks. Tree cut and butted, poor condition. Found stump hole for Sugar B.T.

N44°E 25 Lks. Cor. found and wit. 9/9/58 with Bill Wallace,

Ass't D.F.

SURVEYORS SEAL

SIGNED\_\_\_\_\_Billy D. Buckler\_\_\_\_\_ DATE \_7/28.

REGISTERED LAND SURVEYOR