and the same and the same of t	
SECTION	É

Allegan County Remonumentation

<u> 00 FEB - 1 AN 8:38</u>

LAND CORNER I	RECORDATION	1 CERTIFICATE
Filing Requirem		

For corners in Allegan Corner Code # M-10 (E 1/4 25) Located in: Allegan Twp. 13W 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

CIMM / DE DIDEN

4. Lot No,	Recorded Plat
5 Private Claims	

conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

,	A B		: D	E	E	' G	Н		J	K	L	M
1	$\neg \neg$		1	$\neg$					_			- {
2	— <del>č</del>	⋾⊣	— <u> </u>	-	- 4	-	3	'-	2 I	-	1	. –
3	-											$\dashv$
4	_	;	- 8	$\dashv$	¦	<b>ا</b> ـــد	1	اــــ	1 	1	1	2
5		_										$\dashv$
6	1	) 8	—ı,	7-	1	6	1	5-	—-1	4—-	—ı',	3—
7			-	$\Box$								
8	_1	9	2	0_		1	2	2	2	3	_2	4—
9			<u> </u>			_						
10	3	 	-2	9	2	8	2	7	2	6	2	5—
11		}	<u> </u>						-	<u> </u>		
12	<del> </del> 3	1	_з	2—	<del></del> 3	3—	3	4	3	5	—з	6—
	1		1	Ì	ĺ		l	ĺ	{			

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1831 L.Lyons DS

1. E.P. Waterman 1890 Stake with 3 stones

2. Old notes 79.20' jog

Set corner Lynn 9 S67W 6

Do. 9 N22W 9

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  $M\!-\!10$  . Found nothing at this position

A-10 Watson Twp. North 77'±

Set Standard Allegan Co. Mon. (3/4" x 24" Iron Rod with Remon.cap) on a line as defined by the Northeast corner of Section 25, Allegan Twp (M-9) and the found West 1/4 corner of Section 30, Watson Twp (A-10); and a split of the mile distance from NE corner Sec. 25 (M-9) and the SE corner of Sec. 25 (M-11). The corner position falls 75.66' South of the corner position of A-10, Watson Twp.

This corner is accepted as a careful and faithful reestblishment of the position of the original corner.

Peer group approved August 10, 1999

Dist to M-9 =  $2651.20^{\circ}$ 

Dist to M-11= 2651.20

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Standard Allegan Co. Mon. (3/4" x 24" Iron Rod with Remon.cap) M-10 N36°E 83.52'

Set nail & Allegan Co. Remon. tag in W. side P.Pole

Set nail & Allegan Co. Remon. tag in W. side P.Pole Set nail & Allegan Co. Remon. tag in W. side P.Pole N7°E 396.68

S11°W 383.77

333.00 S14°E

NE corner house siding West 1/4 corner Section 30, Watson Twp (A-10)

North 75.66'

On tree and fence line to West On centerline of Blacktop road APPROVED REMONUMENTATION CORNER

P.A. 345 OF 1990 ALLEGAN COUNTY ANG DATE APPROVED

JERBER SSIONA VEYOR 15.3

COUNTY REP.

Surveyor's Michigan License No.

Signed by

39085