LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Allegan	Located In:	Corner Code -##
(County)		
Public Land Survey	T 2N R _15W.	. F12
	T R	
	T , R	
	T R	
2. Property Controlling	S., 33 T 2N R.,15W.	8
in Section	S T R	
3. Miscellaneous	S , T , , R	·
Property in Sec.	S T R	
Property in Sec.	3 F R	

Register of Deeds Stamp & File Number

___, in a field survey on _____January_22, _1993 _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

5. Private Claims

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

12

A. Description of original monument and accessories and/or subsequent restoration:

F12: Post not established by U.S. Government Survey. Old Allegan County Survey records call for a Oak stake - no accessories (not dated). Other undated Allegan County Surveyor Records indicate a "Stake & Crockery - accessories: 15" W. Oak WSW 58.9", St. Sign NNR 30'. 12" B. Oak SW 39.4'. 6" B. Oak SSE 60'". Records obtained from Wightman-Moored (dated 1973) state "Found 5/8" Iron - accessories: Street sign N208 29.90', 10" Pine S208 59.9', 16" B. Oak S15W 42.70', 18" B. Oak S50W 39.07', 18" W. Oak S75W 58.8', Centerline road 5' North". Corner recorded under Act 132, PA 1970 in Liber 973, Page 489 by J. Dillingham (PS \$16927) as "Found Iron and lists all of Wightman-Moored's accessories.

8: Allegan County Surveyor D. Allen in 1958 performed a survey of the Northwest 1/4 of Section 33 but does not show setting anything. Undated records obtained from Wightman-Moored show "Iron - accessories: 18" Pine SE 83.0', 21" twin Oak NE 34.6', P. pole NW 31.7', 18"

B. Oak NV 44.4".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F12: Found 1" Iron bar and two (2) of Dillingham's accessories. Accepted this corner.

8: Found 1-1/8" Iron pipe on the East-West 1/4 line and 0.25' East of the midpoint between corners E12 and F12 and one (1) witness. Accepted this corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F12: Found 1" Iron bar \$15W 42.70', 16" B. Oak Stump North 3', Centerline Bast-West road \$42W 55.74', Wail & Tag in 10" twin Oak S70W 92.50', Nail & Tag in Power pole North 33.00', MDNR monument S18E 60.12', 17" Pine

OF MICHIG GARY C. BILOW LAND SURVEYOR No. 26453 NOED LAND SURVE

8: Found 1-1/8" Iron pipe and raised with 1/2" x 24" capped rebar N22W 37.66', Nail & Tag in Power pole N27E 45.00°, Nail & Tag in 20° Oak S58E 83.70'. Nail & Tag in 25" Pine North 33.00°, MDNR monument

Surveyor's Michigan License No. .

315/93

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983