* 80	98	
REGISTER OF THE PROPERTY OF TH	98 JAN 21 PH 1:38	FILED


SECTION

Allegan (County)	Located in: Wayland Twp.	Corner Code #	W 21
1. Public Land Survey	T3N R11W TR		MANA TO STATE OF THE O
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR S TR		స్ట్ ట్ర య Register of Deeds Stamp & File Number

, Recorded Plat 4. Lot No. 5. Private Claims

I. Robert Jonker, in a field survey on 12-27, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1831, Sylvester Sibley North between Sec. 1 & 2 40.00 ch. set ½ post Pine 7 N62W 20 Maple 9 S35E 15	LCRC #1-398 - W&W, 1972 Part A-10" Tamarack NE 24: Part B-Set T iron on c/1 roads N & S & W Part C-Took witnesses 16" Maple S33°E 24.88' 8" Maple S35°W 56.10'
(over)	12" Maple N25°W 58.8'

Part B-reset corners from W&W info. Part C-Took witnesses Nail NE side 18" Maple S30°E Nail N. side 30" Maple N65°E 65.69' Nail N. side 16" Elm S80° W 19.91' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

Found Jonker capped rerod by witnesses listed in "A" above for LCRC #4-37, part "C".

Road has been raised about 3'

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY
DATE APPROVED 4-8-9-7 COUNTY REP.__

Accepted as the best available evidence of the position of the original corner.

Peer group approved April 8, 1997.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Replaced with 3/4"x36" std. Allegan Co. Mon. Found Nail on N. side 36" Maple N 70° E Found Nail on N. side 10" Maple S 45° E Set Nail on E. side 17" Maple S 30° W Set Nail on S. side 26" Maple N 75° W 65.62' 51.06 1 - A.C. tag 66.03 ' 55.94



Signed by Robert J. Jo Surveyor's Michigan License

Dec. 30, 1997 Date_

115TR 0006page 259

Over for Sheet 2

FORM APPROYED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED JAN., 1983

1327 0006 PAGE 260

Part "A" (Cont'd)

1993 - Exxel Eng. Found Iron - no witnesses

Commence

. . .

..