MAR U 7 2000

SECTION

ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P. A. 1870:

8	
FEB -1 III 8	FILED
84 8	

36

10 831 FOR CORNERS IN: LOCATED IN: **CORNER CODE # ALLEGAN COUNTY** T..... R...13W J-13 1. Public Land Survey T..... R..... CO SOUTH 1/4 COR. SECTION 35, T...... R..... MONTEREY TWP. T...... R..... REGISTER OF DEEDS STAMP & FILE NUMBER 2. Property Controlling S......R....... in section S......R..... 3. Miscellaneous S.....R Α В C DF F G Н 1 Property in Sec. 2 6 2 4. Lot No.....,Recorded Plat 3 4 ð 12 5. Private Claims 5 I, Raymond Moored in a field survey on Sept. 23, 1999 do hereby state that under 6 18 17 16 -15 14 13 requirments of P.A 74, Michigan P.A of 1970, corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual 7 of survey instructions of the United States Department of the Interior Bureau of Land management 8 19 20 -22 21 23 -24 or by a decree of a Court of Law and/or that the corner points mentioned in the lines 3, 4, and 5 9 above were in comformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, monumented, recovered, found as expressed below. 30 10 29 28 -27-26 つち

A.Description of original monument and accessories and/or subsequent restoration:

SEE BACK OF SHEET FOR CORNER HISTORY

B.Description of corner evidence found and/or method applied in restoring or reestablishing corner.

Note: Not more than 2 corners, all the same town and range, may be recorded on this certificate.

FOUND POINTED STONE PER #6 & #7 ABOVE. TRUE CORNER POSITION ON SPLIT OF MILE BETWEEN I-13 AND K-13 WOULD FALL APPROXIMATELY 3.3-FEET TO THE EAST OF FOUND CORNER. EXCAVATED AT THAT LOCATION AND FOUND NOTHING.

REPLACED FOUND CORNER WITH STANDARD ALLEGAN COUNTY REMON IRON AND CAP.

ACCEPTED POSITION AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

APPROVED BY ALLEGAN COUNTY REMON PEER GROUP ON DEC.

APPROVED REMONUMENTATION CORNER

P.A. 345 OF 1990 **ALLEGAN COUNTY**

OEC. 14 DATE APPROVED

11

12

31

32

33

COUNTY REP. A. V.

C.Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 3/4" X 36" ALLEGAN COUNTY REMON IRON WITH CAP

S75W -FD. NAIL IN N. SIDE 6" OAK 12 37 -FD. NAIL IN NW SIDE 8" HICKORY -NAIL & TAG IN E. SIDE 8" MAPLE -NAIL & TAG IN SE SIDE 6" OAK 20.95 S55W 22.89 N10W S18E 6.25 -J-1, T.2N., R.13W. WEST 1.68

Date.

Surveyors License No. 26463

Page lofz



ALLEGAN COUNTY MONTEREY TOWNSHIP T.3N., R.13W.

SECTION

J-13

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1. G.L.O.-WEST SOUTH SIDE SEC 35 T3N R13W 40.00 SET QR SEC POST BEECH 15 N4E 11 BEECH 9 N61W 11
 - 2. COUNTY SURVEYOR NOTES, (BLACK BOOK) J-13 TO K-13 = 2667.9' STAKE
 - 3. COUNTY SURVEYOR, IRA CHICHESTER, APRIL 14TH. 1865 FOUND ORIGINAL WITNESSES AT 1/4 POST ON SOUTH LINE ONE WAS BROKEN DOWN, MAPLE 16 IN N40°15'W 36
 - 4. COUNTY SURVEYOR, J.W. HICKS, SEPT. 1, 1869 SHOWS \$ 1/4 CORNER
 - 5. COUNTY SURVEYOR NOTES (BLACK BOOK) 1-13 TO J-13 = 40.05 1/2 J-13 TO K-13 = 40.21 1-13 TO K-13 = 80.255
 - 6. ROBERT J. JONKER, L.C.R.C. REC. LIBER 4, PAGE 56 6-5-89 FOUND POINTED ROCK 1.7' E. OF AXLE SHAFT NAIL-N. SIDE 6" OAK \$75°W 12.37' NAIL-NW SIDE 6" HICK \$55°W 20.95' NAIL-N SIDE 6" MAPLE N10°W 22.89'
 - 7. HOLLAND ENGINEERING WITNESS CARD FD. POINTED ROCK JONK 89 NAIL N. SIDE 6" OAK S75W 12:37 NAIL NW SIDE 8" HICKORY S55W 20:95 NAIL N SIDE 6" MAPLE N1DW 22:89



LIBEROUG 7 PARES 9 7